

DEALER DIRECT TRANSPORTATION LLC

39506 N Daisy Mountain Dr, STE 122
Anthem, Arizona 85086
Phone: +14808857561
Email: patrick@dealerdirecttransport.com



BILL OF LADING / VEHICLE INSPECTION REPORT

LOAD ID: 43413				
ORIGIN Experience Wholesale 1210 S Andrews Ave Pompano Beach, FL 33069 Contact: Denes Phone: 954-397-1833		DESTINATION Lifted Trucks 401 NE Loop 820 Hurst, TX 76053 Contact: Lifted Trucks Phone: (817) 864-8795		
VIN 1FMDE4EP8RLA75164	Year / Make / Model 2024 Ford Bronco	Type SUV	Color	Odometer
Inspection notes:				
- BR-Broken - CH-Chipped - CR-Cracked - D-Dented - F-Faded - FF-Foreign Fluid - FT-Flat Tire - G-Gouge - HD-Hail Damage - LC-Loose Contents - M-Missing - MD-Major Damage - MS-Multiple Scratches - O-Other - PC-Paint Chip - R-Rubbed - RU-Rust - S-Scratched - SC-Scuffed		NO INSPECTION DAMAGE MARKINGS		
CR Circles — pickup damages; CR Rounded rectangles — delivery damages; See inspection photos and details: https://bol.superdispatch.com/jWLBbP14wNxjGgElmnXIkI8				
Notes: Closed on July 3rd CALL DANISH TO SCHEDULE PICK UPS OR DELIVERIES CLOSE AT 4:30 PM MON-FRI Closed ...		Notes:		
I agree with the Driver's assessment of the condition of this vehicle. Origin Signature / Jul 2, 2026 / Jordan 		Vehicle received in good condition except as noted above. Destination Signature / Jul 6, 2026 / Lifted Trucks		
Driver Signature / Jul 2, 2026 / Andy Lemus 		Driver Signature / Jul 6, 2026 / Andy Lemus		

DEALER DIRECT TRANSPORTATION LLC

39506 N Daisy Mountain Dr, STE 122
Anthem, Arizona 85086
Phone: +14808857561
Email: patrick@dealerdirecttransport.com



BILL OF LADING / VEHICLE INSPECTION REPORT

LOAD ID: 43413				
ORIGIN Experience Wholesale 1210 S Andrews Ave Pompano Beach, FL 33069 Contact: Denes Phone: 954-397-1833		DESTINATION Lifted Trucks 401 NE Loop 820 Hurst, TX 76053 Contact: Lifted Trucks Phone: (817) 864-8795		
VIN 1FTFW1RG3RFB89526	Year / Make / Model 2024 Ford F-150	Type Pickup (4 doors)	Color	Odometer
Inspection notes:				
BR-Broken CH-Chipped CR-Cracked D-Dented F-Faded FF-Foreign Fluid FT-Flat Tire G-Gouge HD-Hail Damage LC-Loose Contents M-Missing MD-Major Damage MS-Multiple Scratches O-Other PC-Paint Chip R-Rubbed RU-Rust S-Scratched SC-Scuffed NO INSPECTION DAMAGE MARKINGS CR Circles — pickup damages; CR Rounded rectangles — delivery damages; See inspection photos and details: https://bol.superdispatch.com/jWLBbP14wNxjGgElmnXIkI8				
Notes: Closed on July 3rd CALL DANISH TO SCHEDULE PICK UPS OR DELIVERIES CLOSE AT 4:30 PM MON-FRI Closed ...		Notes:		
I agree with the Driver's assessment of the condition of this vehicle. Origin Signature / Jul 2, 2026 / Jordan 		Vehicle received in good condition except as noted above. Destination Signature / Jul 6, 2026 / Lifted Trucks		
Driver Signature / Jul 2, 2026 / Andy Lemus 		Driver Signature / Jul 6, 2026 / Andy Lemus		