

DEALER DIRECT TRANSPORTATION LLC

39506 N Daisy Mountain Dr, STE 122
Anthem, Arizona 85086
Phone: +14808857561
Email: patrick@dealerdirecttransport.com



BILL OF LADING / VEHICLE INSPECTION REPORT


LOAD ID: 43782				
ORIGIN EXPERIENCE WHOLESale 1210 S ANDREWS AVE Pompano Beach, FL 33069 Contact: DANISH Phone: 954-397-1833		DESTINATION Beaver Toyota of Cumming 1875 Buford Hwy Cumming, GA 30041 Contact: Beaver Toyota of Cumming Phone: 470) 533-2060		
VIN JTEVA5BRXS5030684	Year / Make / Model 2025 Toyota 4Runner	Type SUV	Color	Odometer 17373
Inspection notes:				
BR-Broken CH-Chipped CR-Cracked D-Dented F-Faded FF-Foreign Fluid FT-Flat Tire G-Gouge HD-Hail Damage LC-Loose Contents M-Missing MD-Major Damage MS-Multiple Scratches O-Other PC-Paint Chip R-Rubbed RU-Rust S-Scratched SC-Scuffed ● Circles — pickup damages; ■ Rounded rectangles — delivery damages; See inspection photos and details: https://bol.superdispatch.com/rYEzKWwJDz1y0a6xemrgKko13				
Notes: CALL DANISH TO SCHEDULE PICK UPS CLOSE AT 4:30 PM MON-FRI or speak with Jordan		Notes: Drivers - Make sure vehicles are not being dropped off in front of our collision center! They shoul...		
I agree with the Driver's assessment of the condition of this vehicle. Origin Signature / Jul 13, 2026 / Jordan 		Vehicle received in good condition except as noted above. Destination Signature / Jul 15, 2026 / Beaver Toyota of Cumming		
Driver Signature / Jul 13, 2026 / Edward Hanna 		Driver Signature / Jul 15, 2026 / Edward Hanna		

DEALER DIRECT TRANSPORTATION LLC

39506 N Daisy Mountain Dr, STE 122
Anthem, Arizona 85086
Phone: +14808857561
Email: patrick@dealerdirecttransport.com



BILL OF LADING / VEHICLE INSPECTION REPORT

LOAD ID: 43782				
ORIGIN EXPERIENCE WHOLESALE 1210 S ANDREWS AVE Pompano Beach, FL 33069 Contact: DANISH Phone: 954-397-1833		DESTINATION Beaver Toyota of Cumming 1875 Buford Hwy Cumming, GA 30041 Contact: Beaver Toyota of Cumming Phone: 470) 533-2060		
VIN 7SVAAABA6RX036539	Year / Make / Model 2024 Toyota Sequoia	Type SUV	Color	Odometer 25225
Inspection notes:				
BR-Broken CH-Chipped CR-Cracked D-Dented F-Faded FF-Foreign Fluid FT-Flat Tire G-Gouge HD-Hail Damage LC-Loose Contents M-Missing MD-Major Damage MS-Multiple Scratches O-Other PC-Paint Chip R-Rubbed RU-Rust S-Scratched SC-Scuffed  CR Circles — pickup damages; CR Rounded rectangles — delivery damages; See inspection photos and details: https://bol.superdispatch.com/rYEzKWwJDz1y0a6xemrgKko13				
Notes: CALL DANISH TO SCHEDULE PICK UPS CLOSE AT 4:30 PM MON-FRI or speak with Jordan		Notes: Drivers - Make sure vehicles are not being dropped off in front of our collision center! They shoul...		
I agree with the Driver's assessment of the condition of this vehicle. Origin Signature / Jul 13, 2026 / Jordan 		Vehicle received in good condition except as noted above. Destination Signature / Jul 15, 2026 / Beaver Toyota of Cumming		
Driver Signature / Jul 13, 2026 / Edward Hanna 		Driver Signature / Jul 15, 2026 / Edward Hanna		

DEALER DIRECT TRANSPORTATION LLC

39506 N Daisy Mountain Dr, STE 122
Anthem, Arizona 85086
Phone: +14808857561
Email: patrick@dealerdirecttransport.com



BILL OF LADING / VEHICLE INSPECTION REPORT

LOAD ID: 43782				
ORIGIN EXPERIENCE WHOLESALE 1210 S ANDREWS AVE Pompano Beach, FL 33069 Contact: DANISH Phone: 954-397-1833		DESTINATION Beaver Toyota of Cumming 1875 Buford Hwy Cumming, GA 30041 Contact: Beaver Toyota of Cumming Phone: 470) 533-2060		
VIN 5TDYRKEC2RS215638	Year / Make / Model 2024 Toyota Sienna	Type Van	Color	Odometer 46364
Inspection notes:				
BR-Broken CH-Chipped CR-Cracked D-Dented F-Faded FF-Foreign Fluid FT-Flat Tire G-Gouge HD-Hail Damage LC-Loose Contents M-Missing MD-Major Damage MS-Multiple Scratches O-Other PC-Paint Chip R-Rubbed RU-Rust S-Scratched SC-Scuffed CR Circles — pickup damages; CR Rounded rectangles — delivery damages; See inspection photos and details: https://bol.superdispatch.com/rYEzKWwJDz1y0a6xemrgKko13				
Notes: CALL DANISH TO SCHEDULE PICK UPS CLOSE AT 4:30 PM MON-FRI or speak with Jordan		Notes: Drivers - Make sure vehicles are not being dropped off in front of our collision center! They shoul...		
I agree with the Driver's assessment of the condition of this vehicle. Origin Signature / Jul 13, 2026 / Jordan 		Vehicle received in good condition except as noted above. Destination Signature / Jul 15, 2026 / Beaver Toyota of Cumming		
Driver Signature / Jul 13, 2026 / Edward Hanna 		Driver Signature / Jul 15, 2026 / Edward Hanna		

DEALER DIRECT TRANSPORTATION LLC

39506 N Daisy Mountain Dr, STE 122
Anthem, Arizona 85086
Phone: +14808857561
Email: patrick@dealerdirecttransport.com



BILL OF LADING / VEHICLE INSPECTION REPORT

LOAD ID: 43782				
ORIGIN EXPERIENCE WHOLESALE 1210 S ANDREWS AVE Pompano Beach, FL 33069 Contact: DANISH Phone: 954-397-1833		DESTINATION Beaver Toyota of Cumming 1875 Buford Hwy Cumming, GA 30041 Contact: Beaver Toyota of Cumming Phone: 470) 533-2060		
VIN 2T3J1RFVXRW471056	Year / Make / Model 2024 Toyota RAV4	Type SUV	Color	Odometer 50960
Inspection notes:				
BR-Broken CH-Chipped CR-Cracked D-Dented F-Faded FF-Foreign Fluid FT-Flat Tire G-Gouge HD-Hail Damage LC-Loose Contents M-Missing MD-Major Damage MS-Multiple Scratches O-Other PC-Paint Chip R-Rubbed RU-Rust S-Scratched SC-Scuffed CR Circles — pickup damages; CR Rounded rectangles — delivery damages; See inspection photos and details: https://bol.superdispatch.com/rYEzKWwJDz1y0a6xemrgKko13				
Notes: CALL DANISH TO SCHEDULE PICK UPS CLOSE AT 4:30 PM MON-FRI or speak with Jordan		Notes: Drivers - Make sure vehicles are not being dropped off in front of our collision center! They shoul...		
I agree with the Driver's assessment of the condition of this vehicle. Origin Signature / Jul 13, 2026 / Jordan 		Vehicle received in good condition except as noted above. Destination Signature / Jul 15, 2026 / Beaver Toyota of Cumming		
Driver Signature / Jul 13, 2026 / Edward Hanna 		Driver Signature / Jul 15, 2026 / Edward Hanna		