

FURU GROUP INC

3104 N Pleasantburg Dr
Greenville, South Carolina 29609
MC Number: 1177540
Phone: +1 (864) 608-4640
Email: dispatch@furu-group.com



BILL OF LADING / VEHICLE INSPECTION REPORT


LOAD ID: 44083				
ORIGIN Experience Wholesale 1210 S Andrews Ave Pompano Beach, FL 33069 Contact: Denes Phone: 954-397-1833		DESTINATION Foreign Cars Italia of Greensboro 5603 Roanne Way A Greensboro, NC 27409 Contact: Foreign Cars Italia of Greensboro Phone: (336) 717-0147		
VIN W1K6G7GB0SA342895	Year / Make / Model 2025 Mercedes-Benz S-Class	Type Sedan	Color	Odometer 3314
Inspection notes:				
BR-Broken CH-Chipped CR-Cracked D-Dented F-Faded FF-Foreign Fluid FT-Flat Tire G-Gouge HD-Hail Damage LC-Loose Contents M-Missing MD-Major Damage MS-Multiple Scratches O-Other PC-Paint Chip R-Rubbed RU-Rust S-Scratched SC-Scuffed NO INSPECTION DAMAGE MARKINGS CR Circles — pickup damages; CR Rounded rectangles — delivery damages; See inspection photos and details: https://bol.superdispatch.com/eYIXL18LdvLBb3eKjL3gZqRBD				
Notes: CALL DANISH TO SCHEDULE PICK UPS OR DELIVERIES CLOSE AT 4:30 PM MON-FRI Closed on the weekends		Notes:		
I agree with the Driver's assessment of the condition of this vehicle. Origin Signature / Jul 15, 2026 / Denes Dombai 		Vehicle received in good condition except as noted above. Destination Signature / Jul 16, 2026 / Foreign Cars Italia of Greensboro		
Driver Signature / Jul 15, 2026 / Ruslan Abusev 		Driver Signature / Jul 16, 2026 / Ruslan Abusev		

FURU GROUP INC

3104 N Pleasantburg Dr
Greenville, South Carolina 29609
MC Number: 1177540
Phone: +1 (864) 608-4640
Email: dispatch@furu-group.com



BILL OF LADING / VEHICLE INSPECTION REPORT

LOAD ID: 44083				
ORIGIN Experience Wholesale 1210 S Andrews Ave Pompano Beach, FL 33069 Contact: Denes Phone: 954-397-1833		DESTINATION Foreign Cars Italia of Greensboro 5603 Roanne Way A Greensboro, NC 27409 Contact: Foreign Cars Italia of Greensboro Phone: (336) 717-0147		
VIN WP1AF2A55PLB57068	Year / Make / Model 2023 Porsche Macan	Type SUV	Color	Odometer 16291
Inspection notes:				
- BR-Broken - CH-Chipped - CR-Cracked - D-Dented - F-Faded - FF-Foreign Fluid - FT-Flat Tire - G-Gouge - HD-Hail Damage - LC-Loose Contents - M-Missing - MD-Major Damage - MS-Multiple Scratches - O-Other - PC-Paint Chip - R-Rubbed - RU-Rust - S-Scratched - SC-Scuffed		 NO INSPECTION DAMAGE MARKINGS		
CR Circles — pickup damages; CR Rounded rectangles — delivery damages; See inspection photos and details: https://bol.superdispatch.com/eYIXL18LdvLBb3eKjL3gZqRBD				
Notes: CALL DANISH TO SCHEDULE PICK UPS OR DELIVERIES CLOSE AT 4:30 PM MON-FRI Closed on the weekends		Notes:		
I agree with the Driver's assessment of the condition of this vehicle. Origin Signature / Jul 15, 2026 / Denes Dombai 		Vehicle received in good condition except as noted above. Destination Signature / Jul 16, 2026 / Foreign Cars Italia of Greensboro		
Driver Signature / Jul 15, 2026 / Ruslan Abusev 		Driver Signature / Jul 16, 2026 / Ruslan Abusev		

