

# Peugeot 207

VIN: **VF3WB9HZC33832918** Diesel

Generated on **2023-08-17 14:35**



**Theft**



**Odometer**



**Financial and legal  
status**



**Damage**



+31

## Data sources

We checked 900+ data sources in **35 countries**

# Theft

Is the vehicle currently marked as stolen? Was it stolen in the past? Has it been recovered?



We didn't find any records that the vehicle was stolen.

**Here's what we checked:**



**Currently wanted as stolen**

✓ No record found



**Stolen in the past**

✓ No record found

Current status unknown



**Stolen in the past**

✓ No record found

Vehicle has been recovered

Police database stolen vehicle **check completed in:**

 **Italy**

 **Slovakia**

 **Sweden**

 **Slovenia**

 **Finland**

 **Czechia**

 **Canada**

 **Romania**

# Odometer


Are there signs of mileage rollbacks or discrepancies?



Last known mileage: 182,493 km



3 mileage records found



#### Odometer records

2007-05      **13 km**

2008-04      **14,300 km**

2023-05      **182,493 km**

## Financial and legal status

Has the vehicle passed its technical inspections? Does it have property rights restrictions or outstanding loans?



Tech inspection is valid

### Legal



### Technical inspection (also known as MOT)

**Passed** 2023-05



Has successfully passed  
technical inspection



### Scrap

✓ No record found

No record that vehicle was  
marked as scrapped



### Exported

✓ No record found

No export records found



### Imported

✓ No record found

No import records found

## Financial restrictions



### Lease

✓ No record found

No data available on  
outstanding loan or  
finance agreement



### Operating-lease

✓ No record found

No record of vehicle being  
on an operating-lease



### Unit-stocking

✓ No record found

No record of vehicle being  
under unit-stocking  
finance

## Damage

Has this vehicle been damaged in the past? What was the value of the damages?



No damage records found

## Damage records



Occasional inaccuracies can occur, especially when checking older vehicles. Underground repair shops may illegally disguise vehicle defects or damages, not recording their existence anywhere. Sometimes, even vehicle VIN plates may be replaced. We have a variety of methods to detect even such crimes, but it's impossible to provide a 100% guarantee.

## Emissions

How much CO<sub>2</sub> emissions do vehicles of this model/year produce?



CO<sub>2</sub> emission tax band: B (136 g/km)

### CO<sub>2</sub> emissions

Your vehicle CO<sub>2</sub>  
emission

**136 g/km** Class **B**

Up to 120

120 - 140

140 - 155

155 - 165

165 - 190

190 - 225

225 and  
over

Emission CO<sub>2</sub> g/km

## Specs & equipment

What specs and equipment are on record for this vehicle?



Check whether the specs and equipment of this vehicle match the facts given by the seller.

## Identification and technical specifications



Make  
**Peugeot**



Model  
**207**



Body type  
**Convertible**



Powertrain  
displacement  
**1.6 L**



Powertrain power  
**80 kW (107 hp)**



Fuel type  
**Diesel**



Transmission type  
**Manual**



Number of seats  
**4**



Engine code  
**10 JB85 3010902**

## Equipment

### GEN DE PRODUS

VEHICUL PARTICULAR

### LINIE DE PRODUS

207

### NIVEL DE ECHIPARE

COUPE CABRIOLET SPORT 2

### TRANSMISIE

CUTIE DE VITEZE MANUALA5

### CULOAREA CAROSERIEI

KTH - VOPSEA GRI THORIUM

### CULOARE GARNISAJ

"FX"

### MOTOR (TIP)

MOTOR TIP DV

### MONOGRAMA

### MARCA COMERCIALA, TIP SUBANSAMBLU

PEUGEOT

### TIP CAROSERIE

COUPE CABRIOLETA 2 USI

### MOTOR

DIESEL TURBO DV6TED4 FILTRU DE PARTICULE

### TIP DE VOPSEA

VOPSEA METALIZATA LACUITA

### TIP ECHIPARE INTERIOARA

PIELE PERFORATA + PIELE CLAUDIA "QD"

### CUTIE DE VITEZE (CARACTERISTICI)

CUTIE DE VITEZE MECANICA BE4 L

### MONOGRAMA COMPLEMENTARA, DIVERSE

FARA MONOGRAMA SUPLIMENTARA

### CUPLU DE TAHOMETRU

## FARA MONOGRAMA

### DETECTOR DE APA IN FILTRUL DE MOTORINA

FARA SISTEM DE DETECTARE APA IN FILTRUL DE MOTORINA

### DEPOLUARE (MOTOR)

DEPOLUARE MOTOR EURO 4

### MOTOR RACIRE

RADIATOR EP:27 - 21 DM2 ALUMINIU BRAZAT

### AUTODIAGNOSTICARE EOBD

AUTODIAGNOSTICARE "EOBD" FARA ACCELEROMETRU

### DEPOLUARE TEHNICA VEHICUL

DEPOLUARE TEHNICA VEHICUL EURO4

### VENTILATOR

1 VENTILATOR CU 2 TURATII 140W AERO CU PALETA

### VARIANTA SOCIATA INJECTIE

SISTEM DE INJECTIE BOSCH

### STOP AND START

FARA SISTEM STOP AND START

### STIL ROATA (JANTA)

ROATA HOCKENHEIM 17 INCI

### JANTA / PNEU DIMENSIUNI

ECHIPARE PNEU 17 INCI

### ROTI MONTATE

ROATA 7 INCI

### INDICATOR DE PIERDERE A PRESIUNII DE UMFLARE

INDICATOR PIERDERE PRESIUNE PNEURI

### ANTIBLOCARE

## FARA C T

### CARBURANT

MOTORINA CALITATE DA/DE/DE+

### CATALIZATOR

CATALIZATOR CU 2 COMPUSI IN FILTRE IMPREGNATE CU PLATINA

### INCALZIRE CIRCUIT GAZE CARTER

FARA SISTEM DE INCALZIRE CIRCUIT DE GAZE CARTER

### DISPOZITIV (ANTIPOLUARE)

RECIRCULARE GAZE DE ESAPAMENT "EGR"

### FILTRU DE PARTICULE

CU FILTRU DE PARTICULE

### RECUPERARE VAPORI DE BENZINA

FARA SISTEM DE RECUPERARE VAPORI DE BENZINA

### FITRU DE REZERVOR

FARA FILTRU REZERVOR

### CUPLU RAPORT

CP 19 X 72

### DIFERENTIAL (CUTIE)

DIFERENTIAL 84

### PNEURI (DIMENSIUNI, TIP)

PNEU 205/45 R17 88W RANFORSAT

### ROATA (TIP)

MONTARE ROATA CU JANTA DIN ALIAJ

### CUTIE DE VITEZE TIP

CUTIE DE VITEZE MANUALA BE4R

### ANTIRULIU FATA

## ANTIBLOCARE ROATA

### FRANA TIP

DISCURI FATA VENTILATE / DISCURI SPATE

### SUSPENSIE

SUSPENSIE NORMALA

### VARIANTA ASOCIATA FRANA

ABS TEVES MK60 O

### AVERTIZOARE

SISTEM DE AVERTIZARE STANDARD

### TRAPA DE PLAFON (ASPECT)

FARA TRAPA DE PLAFON

### DEFLECTOR AERODINAMIC SPATE

MONTARE FARA DEFLECTOR SPATE

### ORNAMENT LATERAL (DIMENSIUNE)

TREAPTA CULOARE ALUMINIU

### PROTECTIE SUB CAROSERIE

ELEMENT DE PROTECTIE DIN MATERIAL  
PLASTIC + ELEMENT DIN SPUMA SUB  
MOTOR

### FUNCTIE COMPLEMENTARA DE RETROVIZOR EXTERIOR

RETROVIZOR EXTERIOR CU PLIERE  
MANUALA

### INSONORIZARE PE MOTOR

ELEMENT DE IZOLARE CAPOTA + ELEMENT  
DE PROTECTIE TERMICA

### STERGATOR DE PROIECTOR

FARA MECANISM DE STERGERE PROIECTOR

### OBTURATOR FATA FATA

FARA OBTURATOR PARTE FRONTALA FATA

### LUNETA (GEAM DE CAPAC DE PORTBAGAJ)

GEAM FIX DE CAPAC DE PORTBAGAJ

## BARA ANTIRULIU FATA DIAMETRU 22

### CURSA MECANISMULUI DE DIRECTIE

CURSA MECANISM DE DIRECTIE 144

### CONTROL DINAMIC AL STABILITATII

CU SISTEM ESP

### PEDALIER (TIP)

PEDALIER ALUMINIU

### ANTENA

ANTENA INTEGRATA

### DECORATIUNE (ADEZIVA)

FARA DECORATIUNE ADEZIVA

### ORNAMENT LATERAL (ASPECT)

ELEMENTE DE PROTECTIE LATERALE  
COLORATE IN MASA

### ORNAMENT DE ROATA (STIL)

FARA CAPAC DE ROATA

### SUPLIMENT DE PROTECTIE (SUB MOTOR)

FARA PROTECTIE SUPLIMENTARA SUB  
MOTOR

### ORNAMENT DE CAP DE TEAVA DE ESAPAMENT

CU ORNAMENT LA IESIRE ESAPAMENT

### STERGATOR PARBRIZ

MECANISM STERGERE PARBRIZ FARA  
SENZOR DE PLOAIE

### STERGATOR DE LUNETA (FUNCTIONARE)

FARA MECANISM DE STERGERE LUNETA

### GEAM DE PAVILION

FARA ELEMENT VITRAT DE PAVILION

### SONDA DE TEMPERATURA EXTERIOARA

CU SONDA DE TEMPERATURA EXTERIOARA



#### BARA DE PROTECTIE

BARA DE PROTECTIE FATA/SPATE SPORT  
ALUMINIU/CULOARE CAROSERIE

#### PROIECTOR ANTICEATA

PROIECTOARE ANTI-CEATA

#### RETROVIZOR EXTERIOR (PARTEA CONDUCATORULUI)

RETROVIZOR EXTERIOR CONDUCATOR CU  
COMANDA ELECTRICA

#### ROATA DE REZERVA

ROATA TIP ROLA

#### RETROVIZOR EXTERIOR (RAZA ZONA CONDUCATOR)

OGLINDA RETROVIZOR EXTERIOR BOMBATA

#### ORNAMENT DE BARA DE PROTECTIE

BARA DE PROTECTIE FARA BANDOUI

#### GEAM LATERAL SPATE (NATURA)

GEAM LATERAL SPATE CARE POATE COBORI

#### ACCES SI PORNIRE CU MAINI LIBERE

FARA ACCES SI PORNIRE MAINI LIBERE

#### TETIERA SPATE

FARA TETIERA SPATE

#### SCAUN SPATE

BANCHETA SPATE PERNA MONOBLOC  
SPATARE SEPARATE CARE NU SE RABATEAZA

#### CENTURA DE SIGURANTA SPATE

CENTURA DE SIGURANTA SPATE 2  
RETRACTOARE 3 PUNCTE + MARTOR  
LUMINOS DE CUPLARE

#### CLIMA (TEMPERATURA AMBIANTA)

TARI CU CLIMA TEMPERATA

#### PORTBAGAJ

MONTARE FARA USA SUPTOR DE BAGAJE

#### PROIECTOR SPECIAL (OPTICA DUBLA)

PROIECTOR CU PARABOLA DUBLA

#### RETROVIZOR EXTERIOR (PARTEA PASAGERULUI)

RETROVIZOR EXTERIOR PASAGER CU  
COMANDA ELECTRICA

#### ACCESORII EXTERIOARE

MANERE EXTERIOARE + RETROVIZOARE  
EXTERIOARE CULOARE CAROSERIE

#### TRAPA DE PLAFON

TRAPA DE PLAFON ESCAMOTABILA

#### GEAM (ASPECT)

FUMURIU + FUMURIU INCHIS

#### GEAM (TIP)

PARBRIZ STRATIFICAT + GEAMURI LATERALE  
SI SPATE SECURIZATE

#### ALARMA ANTIFURT

FARA ALARMA ANTIFURT

#### TETIERA FATA

TETIERA FATA ARTICULATA

#### MASCARE BAGAJE

FARA PANOU DE MASCARE BAGAJE

#### CENTURA DE SIGURANTA FATA

ALARMA CUPLARE CENTURA CONDUCATOR  
+ PASAGER

#### SIGURANTA COPII

FARA SISTEM DE BLOCARE USA PENTRU  
COPIL

#### GRADARE VITEZE

GRADATIE VITEZA IN KM/H

#### AMBALARE SISTEM AUDIO

ALIMENTARE ANTENA RECEPTOR DIFUZOR  
FATA/SPATE TWEETER

#### COMANDA LA DISTANTA

MONTAJ COMANDA LA DISTANTA

#### ECHIPAMENT PLANSA DE BORD

PLANSA DE BORD SOFT CU DECORATIUNE  
GRINIUM

#### TABLOU DE BORD (CARACTERISTICI)

GRADATIE 220 KM/H 140 M/H FUNDAL ALB  
CU CHENAR CROMAT

#### COMANDA DE SISTEM AUDIO

COMANDA SISTEM AUDIO LA DISTANTA

#### INALTARE SCAUN DE PASAGER FATA

SISTEM DE INALTARE PERNA SCAUN  
PASAGER FATA REGLARE PARALELA

#### COMANDA DE SCAUN FATA DE PASAGER

COMANDA MANUALA SCAUN PASAGER FATA

#### REGLARE SCAUN FATA DE PASAGER

SUPORT DE SUSTINERE LATERALA FIXA  
PENTRU PASAGER

#### CONSOLA DE PLAFON

FARA CONSOLA PLAFON

#### SISTEM DE NAVIGATIE

FARA SISTEM DE NAVIGARE

#### ACTIONARE GEAM SPATE

MECANISM DE ACTIONARE GEAM SPATE CU  
COMANDA ELECTRICA

#### ACCESORII (MANERE)

FARA MANERE

#### PARTE CONDUCERE (POST DE CONDUCERE)

VOLAN PE STANGA

#### ILUMINAT COMPARTIMENT DEPOZITARE

ILUMINAT TORPEDOU

#### LUMINI INTERIOARE DIVERSE

LAMPA DE CITIT HARTA

#### DIFUZOR

4 DIFUZOARE FATA (2 TWEETERE + 2 FATA)  
+ 2 DIFUZOARE SPATE

#### INSONORIZARE HABITACLU

ELEMENT DE IZOLARE FONICA TABLIER 5KG  
+ PERETE PROTECTIE POST + PERETE  
DESPARTITOR DINTRE HABITACLU SI  
COMPARTIMENT MOTOR + PEDALIER

#### COMANDA DE SCAUN FATA DE CONDUCATOR

COMANDA SCAUN CU MEMORIE  
CONDUCATOR

#### REGLARE PERNA DE SEZUT FATA CONDUCATOR

SUSTINERE LATERALA FIXA CONDUCATOR

#### COTIERA DE SCAUN FATA

MONTARE FARA COTIERA FATA

#### CD

FARA MONTARE COMPACT DISC

#### BECURI DE PROIECTOR

LAMPA CU HALOGEN

#### ACTIONARE GEAM DE CONDUCATOR

MECANISM ACTIONARE GEAM CONDUCATOR  
CU COMANDA SECVENTIALA

#### ACTIONARE GEAM FATA PASAGER

MECANISM DE ACTIONARE GEAM PASAGER  
FATA CU COMANDA SECVENTIALA

#### OGLINDA DE PARASOLAR

OGLINDA CONDUCATOR + PASAGER  
ILUMINATA CU CAPAC

#### MONTARE TETIERA SPATE

MONTARE FARA TETIERE SPATE

#### AIRBAG LATERAL FATA

AIRBAG DUBLU LATERAL FATA

#### AIRBAG DE PASAGER

AIRBAG LATERAL PASAGER

#### PACHET ECHIPAMENT

FARA PACHET ECHIPAMENT

#### NEUTRALIZARE AIRBAG

DEZACTIVARE MANUALA AIRBAG

#### PLAFONIERA

COMANDA LA DISTANTA A USILOR +  
PLAFONIEREI FATA

#### PROTECTIE POST FATA

FARA GRILA DE SEPARARE

#### RECEPTOR RADIO

SISTEM AUDIO COMPACT DISC RDS  
"RD4/MP3"

#### REGULATOR DE VITEZA

FARA SISTEM DE REGULARIZARE VITEZA

#### RETROVIZOR INTERIOR

RETROVIZOR INTERIOR CU REGLARE  
PENTRU ZI - NOAPTE CU OGLINDA CARE NU  
ESTE CROMATA ELECTROCHIMIC

#### COVORAS DE PODEA (ASPECT)

#### AFISAJ

AFISAJ (RADIO + CEAS + SI SAU T°,CD)

#### INDICATOR DE ULEI

RECEPTOR TEMPORIZAT PENTRU NIVEL +  
TEMPERATURA

#### FOLIE INCALZIRE SCAUN

SCAUN FARA INCALZIRE

#### ILUMINAT JOS HABITACLU

FARA ILUMINAT INFERIOR DE HABITACLU

#### CALCULATOR DE BORD

CU CALCULATOR DE BORD

#### RETROVIZOR EXTERIOR

RETROVIZOR EXTERIOR CU INCALZIRE

#### COMANDA INTERIOARA DE USA (ASPECT)

COMANDA INTERIOARA USA ASPECT  
CROMAT

#### PROIECTOR DIRECTIONAL

CU PROIECTOR DIRECTIONAL

#### DEPOZITARE (POST DE CONDUCERE)

COMPARTIMENT DEPOZITARE OBIECTE  
MARUNTE INCHIS CU CHEIE + REFRIGERAT

#### REFRIGERARE

SISTEM DE REFRIGERARE AUTOMATA

#### INALTARE SCAUN FATA DE CONDUCATOR

RIDICARE SCAUN CONDUCATOR REGLARE  
PARALELA

#### DEPOZITARE (ALTELE)

BUZUNARE PENTRU HARTA PE SPATARELE  
SCAUNELOR FATA

#### AIRBAG DE CONDUCATOR

COVORAS SUPLIMENTAR MOCHETA 1

DEPOZITARE VOLUM DE INCARCARE

CU PLASA IN PORTBAGAJ

PROTECTIE INTERIOARA

FARA PROTECTIE INTERIOARA

DETECTAREA OBSTACOLULUI

FARA SISTEM DE DETECTARE OBSTACOLE

COVORAS DE PODEA

CU COVORAS SUPLIMENTAR

FRECVENTA RADIO

FRECVENTA RADIO EUROPA OCCIDENTALA

VOLANT

VOLAN IMBRACAT IN PIELE

PACHET AMBIANTA

PACHET AMBIANTA FATA

PRIZA AUXILIARA PACK AUDIO

FARA PRIZA AUXILIARA PACHET AUDIO

BATERIE

BATERIE L2 640

ILUMINAT DEOSEBIT

FARA ILUMINAT SPECIAL

MULTIPLEXARE

MONTARE RETEA MULTIPLEXATA CAN CAN

ATMOSFERA

ATMOSFERA NORMALA

PARTEA DE CIRCULATIE

AIRBAG LATERAL CONDUCATOR

TUNER-RADIO

TUNER DUBLU RADIO

INDICATOR DE TEMPERATURA  
EXTERIOARA (GRADARE)

INDICATOR TEMPERATURA EXTERIOARA  
CELSIUS

ADAPTARE GARNITURA

MANER MANETA DE VITEZE ALUMINIU +  
BURDUF PIELE

AMPLIFICATOR-EGALIZATOR

FARA AMPLIFICATOR EGALIZATOR

COMANDA DE BLOCARE

BLOCARE PRIN SIMPLA INCHIDERE +  
AUTOMATA

INCUIERE COMPARTIMENT DEPOZITARE

COMPARTIMENTE DEPOZITARE OBIECTE  
MARUNTE CU SISTEM DE INCUIERE

AIRBAG DE GENUNCHI CONDUCATOR

AIRBAG ZONA GENUNCHI CONDUCATOR

ALTERNATOR

ALTERNATOR CLASA 15

DEMAROR

DEMAROR CLASA 5

FRECVENTA TELECOMANDA BLOCARE  
DESCHIDERI

FRECVENTA TELECOMANDA DE BLOCARE  
433,92 MHZ HETERODINA

CRITERIU FACTORI, CLIENTELA CONCEPTIE  
STANDARD

CONECTOR DE ASCULTARE SISTEM AUDIO

FARA PRIZA PENTRU ACCESORII

SET DE CHEI

CIRCULARE PE DREAPTA

ECHIPAMENT DE PRIM AJUTOR

FARA ECHIPARE DE REZERVA

MONITORIZARE VITEZA

FARA SISTEM DE MONITORIZARE VITEZA

2 CHEI TELECOMANDA DE INALTA  
FRECVENTA

RULARE

DRUM CORECT

MODUL ELECTRONIC (BOÎTIER  
SERVITUDE)

BSI + COM 2005 INEL CU 4 POZITII

# Timeline

3 records found

The timeline of records for this vehicle

## Records

2007-05

 Italy



### Was registered

The record represents an administrative event. This could be related to a change of ownership, documents, etc

2023-05

 Italy



### Was inspected

A technical inspection event (also known as an MOT, roadworthiness test, or emission control test) has been recorded. Both successful and failed instances may be included.

2023-07

 Italy



### Was deregistered

The indicated record represents an administrative event. This could be related to a change of ownership, change of documents, or similar.



### Data sources

We checked 900+ data sources in **35 countries**