



MONITORING

Dashboard

Greenhouses

Devices

Thresholds

Alerts

4

Control Panel

Schedules

Reports

RM

Rosa Méndez
Site Operator

Dashboard

Live overview · last synced 12
sec ago

GH-01 ·
Main Hall

Systems
Online



↗ +1.2°

Temperature

24.5 °C

● Normal



↘ -3%

Humidity

68 %

● Normal



↘ -6%

Soil Moisture

32 %

● Warning




Water

18

●

Climate · 24 hours

Temperature & humidity trend



Recent Alerts

2 critical

[View all alerts](#)

SEVERITY	LOCATION	SOURCE	MESSAGE
● Critical	GH-02 · North Wing	Water Reservoir	Water level below refill threshold
● Warning	GH-02 · North Wing	Soil Probe 4	Soil moisture drop below range
● Warning	GH-01 · Main Hall	Vent Actuator	Temperature trend above threshold