



Inspeccion de Bloque

Revisión de inspeccion nº 1


Empresa: Compass



Block inspection - Punto de inspección demostrador (2025-10-30)

Final Approval Date
2025-10-30

Classification Society

Imágenes Classification Society

2025-10-30

Shipowner



Inspected Block

Assembly and alignment of the components	Throat thicknesses	Pitting in steel plates	Rounding of edges	Removal of welding spatters	Others
✓	✓	✓	✓	✓	✓

Inspected Block Reference	Inspected Block
2025-10-30. Referencia al casco.	

Remarks

Remark Date 1	Revision Date 1	Remark Date 2	Revision date 2
2025-10-29	2025-10-30	2025-10-30	2025-10-30

Description 1	Remarks
2025-10-30. Todo validado	

Name & Signature

Shipyards	Name & Signature
2025-10-30. Murueta	



Classification Society . Name & Signature
2025-10-30. DNV

Shipowner . Name & Signature
2025-10-30. Royal Greenland

Flag . Name & Signature
2025-10-30. Spanish Flag

Quality Book Code
2025-10-30. B-01_1

Quality Book Revision
2025-10-30. B-01_1

Vessel
2025-10-30. B-092



Fecha	Contenido	Etiquetas	Creador
2025-10-30	Block inspection: "Punto de inspección demostrador"	Punto-de-inspección-demostrador block_inspection	pablo.ceballos@compassis.com

Shepherd