

Confined Space Entry Permit — V-401A

Permit No : PTW-2024-11-08
Type : Confined Space Entry
Vessel : Surge drum V-401A
Date : 2024-11-08

3.1 Permit-to-Work

Permit issued 13:40 and signed by the issuing authority and the performing authority. Valid for one shift only.

3.3 Standby Attendant

Standby attendant assigned by name: S. Deshmukh. Stationed at the manway for the full duration of the entry.

Confined Space Entry Permit — V-401A

3.2 Gas Test Log

Time	O2%	LEL%	H2S ppm	CO ppm
13:50	20.9	0	0	0
14:10	20.9	0	0	0
14:22	20.8	0	0	0
--- monitoring gap 14:22 to 14:47 ---				
14:47	20.9	0	0	0
15:05	20.9	0	0	0

3.4 Continuous Monitoring

Continuous atmosphere monitoring required throughout entry. A gap of 25 minutes (14:22 to 14:47) was recorded due to a monitor battery swap and is flagged as a deviation.

Confined Space Entry Permit — V-401A

3.4 Rescue Equipment Checklist

- [x] Tripod and winch rigged
- [x] SCBA sets x2 staged
- [x] Rescue harness donned
- [x] Communications tested

3.5 Post-Entry Closure

Entry completed 15:20. Headcount verified. Permit closed and signed off by the issuing authority at 15:28.