

AI Manufacturing Analytics

MACHINE Report

Generated: 2026-07-20 16:18:21

Machine Report

CNC Lathe A1 (CNC-001)

Status: running
Health: 92.0%
Temperature: 68.2C
Vibration: 1.2 mm/s
Torque: 42.5 Nm
Tool Wear: 125.0
Predictions: 10 (7 failures)

CNC Mill B2 (CNC-002)

Status: running
Health: 88.0%
Temperature: 72.1C
Vibration: 1.5 mm/s
Torque: 38.0 Nm
Tool Wear: 210.0
Predictions: 10 (5 failures)

Press P1 (PRS-001)

Status: running
Health: 78.0%
Temperature: 55.3C
Vibration: 2.1 mm/s
Torque: 85.0 Nm
Tool Wear: 340.0
Predictions: 10 (2 failures)

Press P2 (PRS-002)

Status: down
Health: 45.0%
Temperature: 95.0C
Vibration: 4.8 mm/s
Torque: 0.0 Nm
Tool Wear: 890.0
Predictions: 10 (6 failures)

Welder W1 (WLD-001)

Status: running
Health: 85.0%

Temperature: 82.5C
Vibration: 1.8 mm/s
Torque: 15.2 Nm
Tool Wear: 450.0
Predictions: 10 (6 failures)

Assembly R1 (ASM-001)

Status: running
Health: 96.0%
Temperature: 38.0C
Vibration: 0.5 mm/s
Torque: 8.5 Nm
Tool Wear: 60.0
Predictions: 10 (5 failures)

Packaging L1 (PKG-001)

Status: idle
Health: 93.0%
Temperature: 32.0C
Vibration: 0.4 mm/s
Torque: 5.2 Nm
Tool Wear: 30.0
Predictions: 10 (5 failures)

Laser Cutter L1 (LSR-001)

Status: running
Health: 90.0%
Temperature: 42.0C
Vibration: 0.7 mm/s
Torque: 0.0 Nm
Tool Wear: 180.0
Predictions: 10 (8 failures)