

NEN2767 Inspection Report

Property Information

Address: Sint Janssingel 92

City: den Bosch

Inspection Date: 18/12/2024

Condition Assessment

Structural Defects: 5/6

Decay Magnitude: 2/6

Defect Intensity: 5/6

Maintenance Assessment

Maintenance needed: Yes

Costs: €

Description

test

