

# NEN2767 Inspection Report

## Property Information

Address: Effestraat 1

City: Eindhoven

Inspection Date: 23/11/2024

## Condition Assessment

Structural Defects: 5/6

Decay Magnitude: 3/6

Defect Intensity: 3/6

## Description

another new tet

## Location Data

Latitude: 51.5670016

Longitude: 5.111808

## Inspection Photo

