

NEN2767 Inspection Report

Property Information

Address: Bernstraat 77 1

City: Oisterwijk

Inspection Date: 01/12/2024

Condition Assessment

Structural Defects: 3/6

Decay Magnitude: 3/6

Defect Intensity: 3/6

Description

Neen

Location Data

Latitude: 51.38423991786853

Longitude: 5.704004151583396