

NEN2767 Inspection Report

Property Information

Address: Effestraat 1 1

City: Eindhoven

Inspection Date: 24/11/2024

Condition Assessment

Structural Defects: 6/6

Decay Magnitude: 3/6

Defect Intensity: 3/6

Description

test4

Location Data

Latitude: 51.5670016

Longitude: 5.111808

Inspection Photo

