

NEN2767 Inspection Report

Property Information

Address: Effestraat 1 1

City: Eindhoven

Inspection Date: 03/12/2024

Condition Assessment


Structural Defects: 1/6

Decay Magnitude: 3/6

Defect Intensity: 3/6

Description

bad



Location Data

Latitude: 51.5637248

Longitude: 5.1019776