



IDS outcome audit (compact)



Validation run: 2026-09-30T23:18:00.892Z
Models: building-architecture.ifc

Wall Name exists		4/4 · 100%
Name		4/4 · 100%
Wall Name is plumbing wall		1/4 · 25%
Name		1/4 · 25%

IDS outcome audit (long)




Validation run: 2026-09-30T23:18:00.892Z
Models: building-architecture.ifc

Wall Name exists
Checked 4 · Passed 4 · Failed 0 · 100%
Attribute ""Name"" must exist
Attribute ""Name"" must exist
Checked 4 · Passed 4 · Failed 0 · 100%

Wall Name is plumbing wall
Checked 4 · Passed 1 · Failed 3 · 25%
Attribute ""Name"" must equal "plumbing wall"
Attribute ""Name"" must equal "plumbing wall"
Checked 4 · Passed 1 · Failed 3 · 25%

Information outcome audit (compact)



Validation run: 2026-09-30T23:18:00.896Z
Models: building-architecture.ifc

Description exists		4/4 · 100%
Name is plumbing wall		1/4 · 25%
(Warning) Description mentions plumbing		1/4 · 25%

Information outcome audit (long)



Checked 12 · Passed 6 · Failed 3 · Warnings 3 · 50% passed

Validation run: 2026-09-30T23:18:00.896Z
Models: building-architecture.ifc

Description exists

Checked 4 · Passed 4 · Failed 0 · 100%

Name is plumbing wall

Checked 4 · Passed 1 · Failed 3 · 25%

Description mentions plumbing

Warning · Checked 4 · Passed 1 · Warnings 3 · 25%