





MAINTENANCE CHECKLIST

Report ID: MC-2025-001

EQUIPMENT INFORMATION

CUSTOMER NAME ACME Manufacturing Corp	EQUIPMENT MODEL HydraulicPress-5000X
SERIAL NUMBER HP5000X-2024-789	TECHNICIAN John Smith, Certified Technician
DATE 2025-09-17	LOCATION Factory Floor - Section A

CHECKLIST ITEMS

Oil Level Check ' Oil level normal - 85%	
Pressure Gauge Reading 2400 PSI - Within normal range	
Hydraulic Hoses Inspection ' PASSED	
Electrical Connections Check ' PASSED	
Safety Systems Test ' FAILED	
Emergency Stop Test ' PASSED	

<div><div>Filter Condition</div><div>Filter replaced - new filter installed</div></div>	
<div><div>Temperature Reading</div><div>68°F - Normal operating temperature</div></div>	
<div><div>Noise Level</div><div>Normal operation - no unusual sounds</div></div>	
<div><div>Vibration Check</div><div>' PASSED</div></div>	<div><div></div></div>
<div><div>General Cleanliness</div><div>' PASSED</div></div>	<div><div></div></div>
<div><div>Photo Documentation</div><div>Multiple photos taken of key components (See Photo 1 on page 2)</div></div>	
<div><div>Review</div><div>Equipment inspection completed successfully. All major systems functioning within normal parameters. Hydraulic fluid levels adequate, electrical connections secure. Safety stop button tested and working properly. Recommend next inspection in 6 months. Note: One pressure sensor reading slightly elevated but within acceptable range - monitor during next inspection.</div></div>	
<div>TECHNICIAN REVIEW</div>	
<div></div>	
<div></div>	
<div><div>TECHNICIAN SIGNATURE</div><div>John Smith, Certified Technician</div></div>	<div><div>DATE COMPLETED</div><div>2025-09-17</div></div>

PHOTOGRAPHIC DOCUMENTATION

Photo 1: Hydraulic pump and pressure gauge

Image not available

Photo 2: Control panel and safety systems

Image not available

Photo 3: Overall equipment condition

Image not available

