





# MAINTENANCE CHECKLIST

Report ID: MC-2025-001

## EQUIPMENT INFORMATION

<b>CUSTOMER NAME</b> ACME Manufacturing Corp	<b>EQUIPMENT MODEL</b> HydraulicPress-5000X
<b>SERIAL NUMBER</b> HP5000X-2024-789	<b>TECHNICIAN</b> John Smith, Certified Technician
<b>DATE</b> 2025-09-17	<b>LOCATION</b> Factory Floor - Section A

## CHECKLIST ITEMS

<b>Oil Level Check</b> ' Oil level normal - 85%	
<b>Pressure Gauge Reading</b> 2400 PSI - Within normal range	
<b>Hydraulic Hoses Inspection</b> ' PASSED	
<b>Electrical Connections Check</b> ' PASSED	
<b>Safety Systems Test</b> ' FAILED	
<b>Emergency Stop Test</b> ' PASSED	

<div><div>Filter Condition</div><div>Filter replaced - new filter installed</div></div>	
<div><div>Temperature Reading</div><div>68°F - Normal operating temperature</div></div>	
<div><div>Noise Level</div><div>Normal operation - no unusual sounds</div></div>	
<div><div>Vibration Check</div><div>' PASSED</div></div>	<div><div></div></div>
<div><div>General Cleanliness</div><div>' PASSED</div></div>	<div><div></div></div>
<div><div>Photo Documentation</div><div>Multiple photos taken of key components (See Photo 1 on page 2)</div></div>	
<div><div>Review</div><div>Equipment inspection completed successfully. All major systems functioning within normal parameters. Hydraulic fluid levels adequate, electrical connections secure. Safety stop button tested and working properly. Recommend next inspection in 6 months. Note: One pressure sensor reading slightly elevated but within acceptable range - monitor during next inspection.</div></div>	
<div>TECHNICIAN REVIEW</div>	
<div></div>	
<div>Equipment inspection completed successfully. All major systems functioning within normal parameters. Hydraulic fluid levels adequate, electrical connections secure. Safety stop button tested and working properly. Recommend next inspection in 6 months. Note: One pressure sensor reading slightly elevated but within acceptable range - monitor during next inspection.</div>	
<div><div>TECHNICIAN SIGNATURE</div><div>John Smith, Certified Technician</div></div>	<div><div>DATE COMPLETED</div><div>2025-09-17</div></div>

# PHOTOGRAPHIC DOCUMENTATION

---

**Photo 1: Hydraulic pump and pressure gauge**

*Image not available*

**Photo 2: Control panel and safety systems**

*Image not available*

### Photo 3: Overall equipment condition

*Image not available*

