



8118 Manning Avenue
Fort McMurray, Alberta T9H 1V7
Phone: (780)791-0430
www.aircontech.com

FIELD REPORT

FS-17-122-260901-PA

Unit # yymmdd

Corresponding Invoice # _____

CUSTOMER		Syncrude Mildred Lake		UNIT No.	17-122
DATE	2026-09-01	CONTACT		MAKE	CAT
CUSTOMER PO #				MODEL	797B
WORK ORDER #	1212			SERIAL No.	JSM00435
Operation #	0010			EQUIP CATEGORY	Truck
NOTIFICATION #	123123			HOUR METER	

QTY.	PART No.	DESCRIPTION	ADMIN	DESCRIPTION OF WORK
1	ACT584500N	Plastic Tamper Seal		C1 - Complaint:
1	ACT584501N	10" Lead Tamper Seal		Perform A101/210 Proof Test
1	ACT500006	LT5RH Exchanged Nitrogen Cartridge		C2 - Cause:
3	ACT581501N	Actuator Cartridge Gasket (Flat Gasket)		Scheduled work
				C3 - Correction
				FLRA, CHAT, Lock out unit, Performed A101/210 Proof Test as per SCL Procedure
				Automatic Shutdown - PASS
				Actuation - PASS
				Manual Shutdown - PASS
				Inspected F/S Component's Firewire, Hoses, Nozzle Caps
				System's all functional
				C4 - Complications: (Minimum of 2)
				Very muddy roads
				Very dusty conditions
				WORK REMAINING

Team: 501D

Performed By: Pavlo Aksonkin PA-90446064 Truck # T-223

Performed By: Truck #

Performed By: Truck #

REG OT STAT

X

TIME IN: TIME OUT:

TIME IN: TIME OUT:

TIME IN: TIME OUT:

Not Responsible for loss or damage to equipment and accessories in case of fire, theft or other cause(s) beyond our control. I hereby authorize the above repair work to be done along with the necessary parts. An express mechanic's lien is hereby acknowledged on the above equipment to secure the repair payment.

Approved by:

Company:

Date:

JOB STATUS: **JOB TYPE:**

X Completed HVAC

Incomplete (SEE WORK REMAINING) X F/S