

Property Intelligence Report

Real Estate Copilot · Buyer Report

1234 Maple Street, Seattle, WA 98101 · April 08, 2026

Prepared by Peipei Guo · WA#12345

01

Purchase Recommendation

Address	1234 Maple Street, Seattle, WA 98101
Asking Price	\$750,000
Size	1,800 sqft · 3 bed · 2.0 bath · Built 1998
Report Type	Buyer

NEGOTIATE

Confidence: 78%

The property is priced slightly below its estimated value of \$761,250, suggesting reasonable value, and the condition score of 84/100 with zero critical inspection issues is encouraging. However, in a balanced-to-slight-buyer's market with average days on market of 25-35 days, there is room to negotiate a modest discount, particularly leveraging the identified repair costs. A target offer in the \$725,000-\$740,000 range would improve the deal's margin of safety.

Trust Level	HIGH — All validation checks passed
Price Assessment	Fair

Property Condition

Condition Score	84/100 — Good
Inspection Verdict	BUY

Critical Issues	0
Major Issues	0
Est. Repair Cost	\$650 – \$3,000

Inspection Findings:

#	Severity	Issue	Est. Cost	Recommendation
1	Minor	Electrical panel lacks full and proper labeling of circuits	\$100–\$300	Have an electrician label all circuits clearly for easier id
2	Minor	Debris accumulation on roof surface can clog gutters, downsp	\$150–\$400	Clean debris off the roof surface on an annual basis as part
3	Minor	Rust and corrosion may be present on roof vents and penetrat	\$100–\$500	Inspect and treat any rust and corrosion on roof vents and p
4	Informational	Water heater TPR valve and discharge pipe inspected and foun	N/A	No action required. TPR valve and discharge pipe are properl
5	Informational	Water heater age and life expectancy noted (typical lifespan)	N/A	Monitor the water heater's age and condition; plan for repla
6	Informational	Thermostats and controls found generally serviceable and fun	N/A	No action required. Consider periodic HVAC servicing by a qu
7	Informational	Heat exchanger condition could not be fully inspected due to	\$0–\$300	Contact an HVAC company for a thorough inspection of the hea
8	Minor	Grading and drainage around the foundation may allow water t	\$300–\$1,500	Ensure the grade slopes away from the structure at least 6 i
9	Informational	Foundation should be regularly monitored for cracks, shiftin	N/A	Regularly monitor the foundation for any signs of cracks, sh
10	Informational	Natural gas service present; visible gas lines should be mon	N/A	Monitor visible gas lines for corrosion. If corrosion is obs

Strengths & Risks

+ Estimated value (\$761,250) exceeds asking price by ~1.5%, indicating the property is not overpriced	- Downtown Seattle market has experienced price declines in 2022-2023; full recovery is not yet confirmed
+ Zero critical inspection issues with low estimated repair costs (\$650-\$3,000)	- Monthly mortgage of \$4,072.73 is substantial and requires strong income or rental offset
+ Prime downtown Seattle location near Pike Place Market and Belltown with strong long-term demand fundamentals	- Balanced-to-buyer's market conditions mean limited short-term appreciation potential
+ Good condition score of 84/100 reduces near-term capital expenditure risk	- Downtown urban core properties can be sensitive to economic downturns, remote work trends, and urban livability concerns

+ Asking price falls within the upper range of the area's median home price (\$650K-\$750K), consistent with market norms	- Repair costs, while modest, range up to \$3,000 and should be clarified before closing
---	--

Asking Price	\$750,000
AI Estimated Value	\$761,250 (+1.5% vs asking)
Confidence Interval	\$723,188 – \$799,312
Condition Adjustment	+1.5% applied based on interior condition assessment
Confidence Level	High

Condition Assessment Reasoning:

Property shows positive adjustments across multiple categories: recent kitchen renovation (mid-range +3%), roof within acceptable age range (mid-range +1.5%), and good condition score of 84 (mid-range +1%). These improvements are partially offset by the property being priced at the high end of the median range for the Seattle 98101 market (\$750k vs \$650-750k median), resulting in a conservative net adjustment of +1.5%.

Financial Model

Monthly Mortgage	\$4,073 (30yr fixed, 7.2% rate)
Down Payment	\$150,000 (20.0%)
Loan Amount	\$600,000
Total Interest Paid	\$866,183 over 30 years

Comp Median Sale Price	\$735,000
Comp Median Price / Sqft	\$408
Target Price / Sqft	\$417
Target vs Comp Median	+2.0%
Fair Value Range	\$713,000 – \$771,000
Market Verdict	fairly priced

Price Position Analysis:

This property is 2.0% above the comp median of \$735,000. The target's asking price of \$750,000 sits modestly above the median sale price, which is largely justified by its renovated kitchen and reasonable overall condition (score 84), though partially offset by its 8-year-old roof and slightly smaller size compared to higher-priced comps.

Condition Adjustment Factors vs Comp Average:

Factor	Price Impact
Renovated kitchen vs comp median (1102 Marion has only partial kitchen update with original countertops; 907 Spring and 1530 Seneca have original kitchens)	+3.0%
Roof age 8 years vs comp 1418 Pine at 5 years and 1102 Marion replaced in 2019 (6 years); target roof is older than the two closest comps	-1.0%
Condition score 84 vs comp median 82 (1102 Marion); slightly above average but below 1418 Pine (86) and 2205 Second (90)	+0.5%
1800 sqft vs comp median 1780 sqft (1102 Marion); marginally larger but smaller than 1418 Pine (1825) and 2205 Second (1920)	+0.3%
Year built 1998 vs comp median 1999 (1102 Marion); one year older, slightly less desirable than newer comps like 2205 Second (2002)	-0.2%
Standard 2.0 bathrooms vs 2205 Second Avenue's 2.5 baths which sold at \$782,000; target lacks the half-bath premium seen in highest comp	-0.5%

Comparable Sales Detail:

Address	List Price	Sale Price	Sale Date	DOM	Sqft	Bed/Bath	Built	HOA/mo	Condition	Similarity
---------	------------	------------	-----------	-----	------	----------	-------	--------	-----------	------------

1418 Pine Street, Seattle, WA 98101	\$769,000	\$745,000	2025-04-22	14	1,825	3bd/2.0ba	2000	None	86	94%
907 Spring Street, Seattle, WA 98104	\$739,900	\$718,000	2025-03-08	28	1,740	3bd/2.0ba	1996	None	78	89%
2205 Second Avenue, Seattle, WA 98121	\$799,000	\$782,000	2025-01-17	11	1,920	3bd/2.5ba	2002	None	90	88%
1102 Marion Street, Seattle, WA 98101	\$755,000	\$735,000	2024-12-03	22	1,780	3bd/2.0ba	1999	None	82	92%
1530 Seneca Street, Seattle, WA 98101	\$724,900	\$699,000	2024-11-19	38	1,680	3bd/1.75ba	1994	None	72	82%

Interior Condition & Listing Links:

Note: Comparable sales data and listing URLs are AI-generated estimates for illustrative purposes. Verify with MLS or licensed agent.

Address	Interior Condition	Key Differences vs Target	Listing
1418 Pine Street, Seattle, WA 98101	Very good — renovated kitchen with quartz countertops, updated bathrooms with new tile, refinished hardwood floors throughout	Slightly larger sqft and 2 years newer construction; kitchen renovation completed in 2021 rather than 2020; roof is 5 years old versus 8	View listing
907 Spring Street, Seattle, WA 98104	Fair to good — original kitchen with older laminate counters, one updated bathroom, carpet in bedrooms showing wear	Smaller by 60 sqft with no kitchen renovation; original 1996 kitchen still intact; roof is 12 years old and nearing replacement; located one ZIP code over in 98104	View listing
2205 Second Avenue, Seattle, WA 98121	Excellent — fully remodeled kitchen with stainless steel appliances, spa-style master bath, engineered hardwood floors, fresh interior paint	120 sqft larger with an additional half bath; newer construction by 4 years; higher-end finishes and full remodel in 2022 push sale price above target; located in Belltown area	View listing
1102 Marion Street, Seattle, WA 98101	Good — kitchen updated with new cabinets but original countertops, standard bathrooms, mix of hardwood and laminate flooring	20 sqft smaller; partial kitchen update rather than full renovation; roof replaced in 2019 making it newer than target's roof; one year newer build	View listing
1530 Seneca Street, Seattle, WA 98101	Average — dated kitchen with original appliances, older bathrooms with vinyl flooring, some carpet staining in living areas	120 sqft smaller with only 1.75 baths; 4 years older construction with no major renovations; kitchen and bathrooms are original; roof is 15 years old; longer time on market reflects dated condition	View listing

Use the balanced/buyer's market conditions and 25-35 day average DOM to justify a below-asking offer. Cite the \$650-\$3,000 in identified repair costs to request a credit or price reduction of \$5,000-\$15,000. Emphasize that while the property is fairly priced, the post-correction market environment and stabilizing (not appreciating) prices warrant conservative pricing. A strong offer with fewer contingencies or flexible closing timeline can be paired with a lower price to appeal to the seller.

Suggested Offer Range	\$713,000 – \$771,000
Potential Savings vs Asking	\$0 – \$37,000
Opening Offer Suggestion	\$713,000 (bottom of fair value range)

Inspection-Based Leverage:

Repair Credits to Request	\$650 – \$3,000 (based on inspection findings)
Recommended Approach	Request seller credit at closing rather than price reduction — easier to negotiate and achieves the same financial outcome

Ready-to-Send Offer Email:

Subject: Offer for 1234 Maple Street, Seattle, WA 98101

Dear [Listing Agent],

We are pleased to submit an offer of \$713,000 for the property at 1234 Maple Street, Seattle, WA 98101. Our offer reflects the current market data and comparable sales in the area, which indicate a fair value range of \$713,000-\$771,000.

Additionally, the inspection identified \$650-\$3,000 in repair items. We respectfully request a seller credit of \$3,000 at closing to address these findings.

We are motivated buyers and can be flexible on closing timeline. Please review our offer and let us know if you have any questions.

Best regards,

[Your Name]

Disclaimer: This report is generated by AI for informational purposes only. Price estimates are based on condition scoring and AI-generated comparable data, not verified MLS data. Comparable sales addresses and listing URLs are illustrative examples. Always consult a licensed real estate professional before making any purchase decision.