



# Shoreline Apartments Blc

Unit 402 · Apartment



DATE OF INSPECTION  
**10 August 2026**



PROPERTY TYPE  
**Apartment**



CONTRACT START  
**1 July 2026**



CONTRACT END  
**30 June 2027**



LANDLORD

**A T A**  
[REDACTED]@m[REDACTED].com



TENANT

**M L Z**  
[REDACTED]@gmail.com

## TENANCY DETAILS

REPORT ID

**SNF-CO-2026-4CEAC50B**

BASELINE REPORT

**SNF-CI-2026-12CDF998 · 10 August 2026**

ANNUAL RENT

**AED 165,000**

TENANCY TYPE

**Standard**

CONTRACT STATUS

**Completed**

EJARI REFERENCE

**TC-2026-05219**

BASELINE INTEGRITY

**SHA-256 2803b78f...9f454130 · Signed by all parties**

SECURITY DEPOSIT

**AED 13,750**

FURNISHED

**Yes**

## ● EXECUTIVE SUMMARY

Check-out inspection of Shoreline Apartments Blc, Unit 402 conducted 10 August 2026: 6 rooms, 9 photos. New damage identified since check-in in the Living Room, specifically a white surface discoloration approximately 15 cm in diameter on the interior window sill; the Laundry room hole in the lower right wall section was present at check-in and remains unchanged, while the Entrance, Kitchen, Bathroom 1, and Bedroom 1 are consistent with check-in condition. 2 furnished items show degradation or loss since check-in, including 1 item missing from the inventory; 1 Access Card was not returned at check-out against 2 issued at check-in, with all Door Keys and the Parking Card fully returned. Closes tenancy record 1 July 2026 to 30 June 2027.



6

ROOMS INSPECTED

9

PHOTOS CAPTURED  
vs check-in: 8

2

FINDINGS FLAGGED  
vs check-in: 1

EVOLUTION SINCE CHECK-IN

Degraded

|                |                                                                                  |
|----------------|----------------------------------------------------------------------------------|
| New<br>1       | Stain · Living Room                                                              |
| Unchanged<br>1 | Hole · Laundry                                                                   |
| Resolved<br>0  | —                                                                                |
| Inventory<br>3 | 3 changes: Sofa (Good ' Fair) · Microwave (Good ' Damaged) · Bed frame (Missing) |
| Keys<br>1      | 1 not returned: Access Card ×1                                                   |

LOCATION VERIFIED

Check-out photos captured at the check-in location

GPS medians compared · 9 of 9 check-out photos with coordinates

ROOM COMPARISON

| Room        | Check-in Photos | Check-out Photos | Findings (inbut) | Verdict   |
|-------------|-----------------|------------------|------------------|-----------|
| Entrance    | 1               | 1                | 0 -> 0           | No change |
| Living Room | 2               | 3                | 0 -> 1           | Degraded  |
| Kitchen     | 1               | 1                | 0 -> 0           | No change |
| Bedroom 1   | 2               | 2                | 0 -> 0           | No change |
| Bathroom 1  | 1               | 1                | 0 -> 0           | No change |
| Laundry     | 1               | 1                | 1 -> 1           | No change |

FURNITURE

2

ITEMS DEGRADED OR MISSING

KEY RETURN

| ITEM         | GIVEN | RETURNED | STATUS     |
|--------------|-------|----------|------------|
| Door Keys    | x2    | x2       | Returned   |
| Parking Card | x1    | x1       | Returned   |
| Access Card  | x2    | x1       | Missing x1 |

● Access Card: missing x1

# Entrance

1 photos captured

0 findings flagged

No change

## CHECK-IN



### CHECK-IN NOTE

ceiling clean · walls clean · floor tiles clean · doors intact · no visible defects

## CHECK-OUT



### CHECK-OUT NOTE

ceiling clean · walls clean · floor tiles clean · doors intact · no visible defects

# Living Room

3 photos captured    1 finding flagged

Degraded

CHECK-IN



CHECK-IN NOTE  
ceiling clean · walls clean · floor tiles clean · no visible defects

CHECK-OUT



CHECK-OUT NOTE  
ceiling clean · walls clean · floor tiles clean · no visible defects

CHECK-IN



CHECK-IN NOTE  
ceiling clean · walls clean · flooring clean · windows intact · fixtures intact · no visible defects

CHECK-OUT




CHECK-OUT NOTE  
ceiling clean · walls clean · flooring clean · windows intact · fixtures intact · no visible defects

# Living Room

3 photos captured

1 finding flagged

## NEW DAMAGE



10 August 2026 at 17:59

## STAIN

### CHECK-OUT NOTE

stain on window sill interior · white surface discoloration ~15cm diameter

# Kitchen

1 photos captured

0 findings flagged

No change

## CHECK-IN



10 August 2026 at 17:44

### CHECK-IN NOTE

ceiling clean · no visible defects · walls intact · countertops clean · floor tiles clean · fixtures operational

## CHECK-OUT



10 August 2026 at 17:59

### CHECK-OUT NOTE

ceiling clean · walls intact · countertops clean · floor tiles clean · fixtures operational · no new defects



# Bedroom 1

2 photos captured    0 findings flagged

No change

CHECK-IN



10 August 2026 at 17:45

CHECK-IN NOTE  
Clean · no visible defects

CHECK-OUT



10 August 2026 at 18:00

CHECK-OUT NOTE  
hole in ceiling ~30cm diameter unchanged since check-in · walls clean · floor clean · no new defects

CHECK-IN



10 August 2026 at 17:45

CHECK-IN NOTE  
ceiling clean · walls clean · floor tiles clean · windows intact · balcony door intact · smoke detector present · no visible defects

CHECK-OUT



10 August 2026 at 17:59

CHECK-OUT NOTE  
ceiling clean · walls clean · floor tiles clean · windows intact · balcony door intact · smoke detector present · no visible defects

# Bathroom 1

1 photos captured    0 findings flagged

No change

## CHECK-IN



### CHECK-IN NOTE

ceiling intact · walls clean · floor tiles clean · bathtub intact · toilet intact · double sink basin intact · mirror intact · fixtures operational · no visible defects

## CHECK-OUT



### CHECK-OUT NOTE

ceiling intact · walls clean · floor tiles clean · bathtub intact · toilet intact · double sink basin intact · mirror intact · fixtures operational · no visible defects



# Laundry

1 photos captured

1 finding flagged

No change

## CHECK-IN



10 August 2026 at 17:47

## HOLE

### CHECK-IN NOTE

Hole in wall, right side lower section ~2cm

## CHECK-OUT



10 August 2026 at 18:01

## HOLE

### CHECK-OUT NOTE

hole in wall right side lower section ~2cm unchanged since check-in

# Check-in vs Check-out

9 items

LIVING ROOM


## Coffee table

Furniture

Check-in: Good → Check-out: Good

● NO CHANGE

CHECK - IN



CHECK - OUT



LIVING ROOM


## Sofa

Furniture

Check-in: Good → Check-out: Fair

● DEGRADED

CHECK - IN



CHECK - OUT



CHECK - OUT NOTE

Sofa has been damaged a bit since check-in, armrest need to be replaced

# Check-in vs Check-out

9 items

LIVING ROOM

TV

Electronics

Check-in: Good → Check-out: Good

● NO CHANGE

CHECK - IN



CHECK - OUT



LIVING ROOM


TV unit

Furniture


Check-in: Good → Check-out: Good

● NO CHANGE

CHECK - IN



CHECK - OUT



# Check-in vs Check-out

9 items

KITCHEN


## Fridge

Appliances

Check-in: Good → Check-out: Good

● NO CHANGE

CHECK - IN



CHECK - OUT



KITCHEN

## Microwave

Appliances

Check-in: Good → Check-out: Damaged

● NEW DAMAGE

CHECK - IN



CHECK - OUT



CHECK - OUT NOTE

Microwave broken need to be replaced



# Check-in vs Check-out

9 items

KITCHEN

## Washing machine

Appliances

Check-in: Good → Check-out: Good

● NO CHANGE

CHECK - IN



CHECK - OUT



BEDROOM 1


## Bed frame

Furniture


Check-in: Good → Check-out: Missing

● MISSING

CHECK - IN



CHECK - OUT





# Check-in vs Check-out

9 items

BEDROOM 1


Bedside table x2

Furniture

Check-in: Good → Check-out: Good

● NO CHANGE

CHECK - IN



CHECK - OUT





**This report has been reviewed  
and agreed upon by all parties.**

Shoreline Apartments Blc · 10 August 2026



### Scan to verify this report

View the original online version, verify document authenticity, and access the full digital record. This QR code links directly to the inspection report on snagify.net.

#### LANDLORD

A ■ ■ ■ T ■ ■ A ■ ■ ■ ■ ■

● Signed on 10 August 2026 at 18:08

#### TENANT

M ■ L ■ Z ■ ■ ■ ■ ■

● Signed on 10 August 2026 at 18:07

#### INSPECTOR

P ■ ■ A ■ ■ ■

Horizon Properties · RERA #123456

● Signed on 10 August 2026 at 18:08

#### DOCUMENT INTEGRITY · SHA-256 HASH



df864f8b30ada7461503b1ef8510d4757076385c696298870b19135f486e0565

This report documents the condition of the property as observed at the time of inspection. It is based on a visual assessment only and does not constitute a structural, electrical, or plumbing survey. All parties are advised to review this report carefully. By signing, each party acknowledges the findings recorded herein.

This document is generated electronically and verified by SHA-256 hash.