

Unit:-II



#### **Batch Report**

: HA-CYL DD **Equipment Type** 

**Equipment Name** 

: Horizontal Cylindrical\_DD

**Batch No** 

: 42

**Start Date Time** 

: 10-09-2020 09:50:24

**End Date Time** 

: 10-09-2020 11:26:36

Log Interval ( sec ) : 60 **Recipe Name** 

: Media

Temp Set Point ( ° C )

: 121

-ve Pulsing

+ve Pulsing

: 2

Hold Time ( min )

: 20

Post VAC Set

: No

: 1

Post VAC Time (min):0

**Operated By** 

: Administrator (admin)

Operator Comments : start batch

| SrNo | Log Date Time<br>dd-MM-yyyy HH:mm:ss | BATCH STATUS | (A) SENSOR | (B) SENSOR<br>° C | DRAIN SENSOR | PRESSURE<br>mbar | F0 VALUE |
|------|--------------------------------------|--------------|------------|-------------------|--------------|------------------|----------|
| 1    | 10-09-2020 09:50:19                  | HEATING      | 32.0       | 32.3              | 30.4         | 978              | 0.00     |
| 2    | 10-09-2020 09:51:19                  | HEATING      | 32.0       | 32.2              | 30.4         | 978              | 0.00     |
| 3    | 10-09-2020 09:52:19                  | HEATING      | 32.0       | 32.2              | 30.5         | 978              | 0.00     |
| 4    | 10-09-2020 09:53:19                  | HEATING      | 31.9       | 32.2              | 30.5         | 978              | 0.00     |
| 5    | 10-09-2020 09:54:19                  | HEATING      | 31.9       | 32.1              | 30.5         | 978              | 0.00     |
| 6    | 10-09-2020 09:55:19                  | HEATING      | 32.0       | 32.1              | 30.6         | 978              | 0.00     |
| 7    | 10-09-2020 09:56:19                  | HEATING      | 31.9       | 32.1              | 30.6         | 978              | 0.00     |
| 8    | 10-09-2020 09:57:19                  | HEATING      | 31.9       | 32.1              | 30.6         | 978              | 0.00     |
| 9    | 10-09-2020 09:58:19                  | HEATING      | 31.8       | 32.0              | 30.7         | 978              | 0.00     |
| 10   | 10-09-2020 09:59:19                  | HEATING      | 31.8       | 32.0              | 30.6         | 978              | 0.00     |
| 11   | 10-09-2020 10:00:19                  | HEATING      | 31.8       | 32.0              | 30.7         | 979              | 0.00     |
| 12   | 10-09-2020 10:01:19                  | HEATING      | 31.8       | 32.0              | 30.7         | 980              | 0.00     |
| 13   | 10-09-2020 10:02:19                  | HEATING      | 31.9       | 32.1              | 30.7         | 985              | 0.00     |
| 14   | 10-09-2020 10:03:19                  | HEATING      | 32.0       | 32.2              | 30.7         | 993              | 0.00     |
| 15   | 10-09-2020 10:04:19                  | HEATING      | 32.2       | 32.3              | 30.8         | 1004             | 0.00     |

|  | SO |  |  |  |
|--|----|--|--|--|
|  |    |  |  |  |

Printed By: Administrator On 10-09-2020 18:25:57





Unit:-II

#### **Batch Report**

Equipment Type : HA-CYL DD Equipment Name : Horizontal Cylindrical\_DD

| SrNo | Log Date Time       | BATCH STATUS | (A) SENSOR<br>° C | (B) SENSOR | DRAIN SENSOR | PRESSURE<br>mbar | F0 VALUE |
|------|---------------------|--------------|-------------------|------------|--------------|------------------|----------|
| 16   | 10-09-2020 10:05:19 | HEATING      | 32.5              | 32.6       | 30.7         | 1018             | 0.00     |
| 17   | 10-09-2020 10:06:19 | HEATING      | 33.0              | 33.1       | 30.8         | 1030             | 0.00     |
| 18   | 10-09-2020 10:07:19 | HEATING      | 34.1              | 34.0       | 30.8         | 1047             | 0.00     |
| 19   | 10-09-2020 10:08:19 | HEATING      | 39.1              | 37.1       | 30.9         | 1050             | 0.00     |
| 20   | 10-09-2020 10:09:19 | HEATING      | 64.4              | 46.3       | 30.9         | 1051             | 0.00     |
| 21   | 10-09-2020 10:10:19 | HEATING      | 70.2              | 56.7       | 31.1         | 1052             | 0.00     |
| 22   | 10-09-2020 10:11:19 | HEATING      | 74.1              | 66.0       | 31.2         | 1049             | 0.00     |
| 23   | 10-09-2020 10:12:19 | HEATING      | 77.2              | 74.1       | 31.2         | 1051             | 0.00     |
| 24   | 10-09-2020 10:13:19 | HEATING      | 81.1              | 80.3       | 31.4         | 1050             | 0.00     |
| 25   | 10-09-2020 10:14:19 | HEATING      | 84.9              | 85.1       | 32.0         | 1050             | 0.00     |
| 26   | 10-09-2020 10:15:19 | HEATING      | 88.1              | 88.7       | 33.6         | 1051             | 0.00     |
| 27   | 10-09-2020 10:16:19 | HEATING      | 91.0              | 91.7       | 34.3         | 1050             | 0.00     |
| 28   | 10-09-2020 10:17:19 | HEATING      | 93.6              | 94.2       | 35.3         | 1050             | 0.00     |
| 29   | 10-09-2020 10:18:19 | -VE_PULSE    | 95.7              | 96.4       | 36.8         | 1004             | 0.00     |
| 30   | 10-09-2020 10:19:19 | +VE_PULSE    | 104.0             | 105.4      | 86.4         | 1585             | 0.00     |
| 31   | 10-09-2020 10:20:19 | +VE_PULSE    | 103.3             | 103.8      | 88.4         | 1454             | 0.00     |
| 32   | 10-09-2020 10:21:19 | +VE_PULSE    | 104.9             | 105.2      | 89.6         | 1456             | 0.00     |
| 33   | 10-09-2020 10:22:19 | +VE_PULSE    | 106.6             | 106.9      | 92.9         | 1475             | 0.00     |
| 34   | 10-09-2020 10:23:19 | +VE_PULSE    | 106.4             | 106.7      | 93.6         | 1443             | 0.00     |
| 35   | 10-09-2020 10:24:19 | +VE PULSE    | 108.6             | 109.0      | 96.6         | 1497             | 0.00     |

| _  |   |     | • . |   | _   |   |
|----|---|-----|-----|---|-----|---|
| _^ |   | iso | ++  | 1 | - ( | ١ |
| _u | u | เอบ | ш   |   | ٠.  | , |





Unit:-II

#### **Batch Report**

Equipment Type : HA-CYL DD Equipment Name : Horizontal Cylindrical\_DD

| SrNo | Log Date Time       | BATCH STATUS | (A) SENSOR | (B) SENSOR | DRAIN SENSOR | PRESSURE<br>mbar | F0 VALUE |
|------|---------------------|--------------|------------|------------|--------------|------------------|----------|
| 36   | 10-09-2020 10:25:19 | +VE PULSE    | 110.4      | 110.7      | 101.3        | 1550             | 0.00     |
| 37   | 10-09-2020 10:26:19 | +VE PULSE    | 112.1      | 112.2      | 105.5        | 1611             | 0.00     |
| 38   | 10-09-2020 10:27:19 | +VE PULSE    | 113.5      | 113.7      | 109.3        | 1672             | 0.00     |
| 39   | 10-09-2020 10:28:19 | +VE PULSE    | 115.0      | 115.1      | 112.3        | 1740             | 0.00     |
| 40   | 10-09-2020 10:29:19 | +VE PULSE    | 116.4      | 116.5      | 114.4        | 1793             | 0.00     |
| 41   | 10-09-2020 10:30:19 | +VE PULSE    | 115.0      | 115.1      | 114.2        | 1702             | 0.00     |
| 42   | 10-09-2020 10:31:19 | +VE PULSE    | 115.6      | 115.8      | 115.0        | 1726             | 0.00     |
| 43   | 10-09-2020 10:32:19 | +VE_PULSE    | 116.1      | 116.2      | 115.3        | 1746             | 0.00     |
| 44   | 10-09-2020 10:33:19 | +VE_PULSE    | 115.3      | 115.4      | 114.6        | 1704             | 0.00     |
| 45   | 10-09-2020 10:34:19 | +VE_PULSE    | 116.2      | 116.5      | 115.5        | 1756             | 0.00     |
| 46   | 10-09-2020 10:35:19 | +VE_PULSE    | 110.8      | 111.0      | 110.1        | 1437             | 0.00     |
| 47   | 10-09-2020 10:36:19 | +VE_PULSE    | 106.3      | 106.4      | 105.5        | 1221             | 0.00     |
| 48   | 10-09-2020 10:37:19 | +VE_PULSE    | 116.3      | 116.4      | 115.1        | 1737             | 0.00     |
| 49   | 10-09-2020 10:38:19 | +VE_PULSE    | 115.8      | 115.8      | 115.0        | 1708             | 0.00     |
| 50   | 10-09-2020 10:39:19 | +VE_PULSE    | 116.7      | 116.6      | 115.6        | 1857             | 0.00     |
| 51   | 10-09-2020 10:40:19 | +VE_PULSE    | 117.0      | 116.6      | 115.8        | 1840             | 0.00     |
| 52   | 10-09-2020 10:41:19 | +VE_PULSE    | 116.9      | 117.1      | 116.1        | 1790             | 0.00     |
| 53   | 10-09-2020 10:42:19 | +VE_PULSE    | 112.1      | 112.2      | 111.2        | 1479             | 0.00     |
| 54   | 10-09-2020 10:43:19 | +VE_PULSE    | 107.2      | 109.8      | 106.2        | 1245             | 0.00     |
| 55   | 10-09-2020 10:44:19 | TEMP RISE    | 119.9      | 120.1      | 118.4        | 1957             | 0.00     |

| _   |      |             |   | _  |
|-----|------|-------------|---|----|
| -01 | Jiso | <b>↑</b> tt | 1 | (1 |
|     |      |             |   |    |



equitron\*

Unit:-II

#### **Batch Report**

Equipment Type : HA-CYL DD Equipment Name : Horizontal Cylindrical\_DD

| SrNo | Log Date Time       | BATCH STATUS | (A) SENSOR | (B) SENSOR | DRAIN SENSOR | PRESSURE<br>mbar | F0 VALUE |
|------|---------------------|--------------|------------|------------|--------------|------------------|----------|
| 56   | 10-09-2020 10:45:19 | TEMP RISE    | 121.7      | 121.8      | 120.8        | 2068             | 0.00     |
| 57   | 10-09-2020 10:45:22 | STERILE      | 121.8      | 121.9      | 121.0        | 2102             | 0.00     |
| 58   | 10-09-2020 10:46:22 | STERILE      | 122.2      | 122.2      | 121.3        | 2161             | 1.32     |
| 59   | 10-09-2020 10:47:22 | STERILE      | 122.6      | 122.6      | 121.8        | 2129             | 2.73     |
| 60   | 10-09-2020 10:48:22 | STERILE      | 122.3      | 122.3      | 121.5        | 2110             | 4.08     |
| 61   | 10-09-2020 10:49:22 | STERILE      | 122.6      | 122.8      | 121.9        | 2133             | 5.56     |
| 62   | 10-09-2020 10:50:22 | STERILE      | 122.5      | 122.5      | 121.7        | 2127             | 6.94     |
| 63   | 10-09-2020 10:51:22 | STERILE      | 121.9      | 122.0      | 121.2        | 2088             | 8.17     |
| 64   | 10-09-2020 10:52:22 | STERILE      | 122.1      | 122.3      | 121.5        | 2104             | 9.46     |
| 65   | 10-09-2020 10:53:22 | STERILE      | 122.5      | 122.6      | 121.8        | 2132             | 10.87    |
| 66   | 10-09-2020 10:54:22 | STERILE      | 122.1      | 122.2      | 121.5        | 2098             | 12.16    |
| 67   | 10-09-2020 10:55:22 | STERILE      | 122.6      | 122.7      | 121.8        | 2127             | 13.57    |
| 68   | 10-09-2020 10:56:22 | STERILE      | 122.3      | 122.4      | 121.6        | 2109             | 14.89    |
| 69   | 10-09-2020 10:57:22 | STERILE      | 122.7      | 122.8      | 121.9        | 2138             | 16.37    |
| 70   | 10-09-2020 10:58:22 | STERILE      | 122.4      | 122.4      | 121.7        | 2122             | 17.72    |
| 71   | 10-09-2020 10:59:22 | STERILE      | 122.2      | 122.4      | 121.6        | 2107             | 19.04    |
| 72   | 10-09-2020 11:00:22 | STERILE      | 122.4      | 122.4      | 121.6        | 2134             | 20.42    |
| 73   | 10-09-2020 11:01:22 | STERILE      | 121.9      | 121.9      | 121.3        | 2115             | 21.65    |
| 74   | 10-09-2020 11:02:22 | STERILE      | 122.1      | 122.2      | 121.6        | 2091             | 22.93    |
| 75   | 10-09-2020 11:03:22 | STERILE      | 122.4      | 122.5      | 121.8        | 2121             | 24.32    |

| _   |      |             |   | _  |
|-----|------|-------------|---|----|
| -01 | Jiso | <b>↑</b> tt | 1 | (1 |
|     |      |             |   |    |





Unit:-II

#### **Batch Report**

Equipment Type : HA-CYL DD Equipment Name : Horizontal Cylindrical\_DD

| SrNo | Log Date Time       | BATCH STATUS | (A) SENSOR<br>° C | (B) SENSOR | DRAIN SENSOR | PRESSURE<br>mbar | F0 VALUE |
|------|---------------------|--------------|-------------------|------------|--------------|------------------|----------|
| 76   | 10-09-2020 11:04:22 | STERILE      | 122.4             | 122.5      | 121.8        | 2126             | 25.70    |
| 77   | 10-09-2020 11:05:22 | STERILE      | 121.8             | 121.9      | 121.3        | 2104             | 26.93    |
| 78   | 10-09-2020 11:06:22 | EXHAUST      | 117.6             | 117.8      | 116.7        | 1785             | 26.93    |
| 79   | 10-09-2020 11:07:22 | EXHAUST      | 112.8             | 113.4      | 111.8        | 1511             | 26.93    |
| 80   | 10-09-2020 11:08:22 | EXHAUST      | 107.6             | 111.0      | 106.4        | 1250             | 26.93    |
| 81   | 10-09-2020 11:09:22 | EXHAUST      | 104.5             | 108.8      | 102.4        | 1081             | 26.93    |
| 82   | 10-09-2020 11:10:22 | EXHAUST      | 102.7             | 106.9      | 100.0        | 999              | 26.93    |
| 83   | 10-09-2020 11:11:03 | EOC          | 101.7             | 105.9      | 99.4         | 981              | 26.93    |




Unit:-II



**Batch Report** 

Equipment Type : HA-CYL DD Equipment Name : Horizontal Cylindrical\_DD





equitron®

Unit:-II

### **Batch Report**

| Equipment Type   |   | : HA-CYL DD           | <b>Equipment Name</b> | : Hori                             | zontal Cylindrical_DD |                       |                      |  |
|------------------|---|-----------------------|-----------------------|------------------------------------|-----------------------|-----------------------|----------------------|--|
| Batch No         |   | : 42                  | Start Date Time       | Start Date Time : 10-09-2020 09:50 |                       | End Date Time         | : 10-09-2020 11:26:3 |  |
| Batch Started By | : | Administrator (admin) |                       |                                    | Batch Stopped By:     | Administrator (admin) |                      |  |
| Batch Started On | : | 10-09-2020 09:50:24   |                       |                                    | Batch Stopped On :    | 10-09-2020 11:26:36   |                      |  |
| Comments         | : | start batch           |                       | Com                                |                       | BATCH STOP            |                      |  |
| Verified By      | : |                       |                       |                                    | _ Approved By :       |                       |                      |  |
| Verified On      | : |                       |                       |                                    | Approved On :         |                       |                      |  |
| Comments         |   |                       |                       |                                    | Comments: :           |                       |                      |  |