

Weather Damage – Sample FNOL Report

Incident: Severe hailstorm damaged roof shingles.

Damage: 40% roof area impacted; 2 broken skylights.

Location: Springfield, IL.

Supporting Evidence: Photos uploaded by policyholder.

Next Steps: Adjuster visit + temporary tarping.