
QA TEST 1 Example Road, QA1 1AA

Project Reference: QA-SAMPLE | NC Reference: NC-02

NON-COMPLIANCE

End caps missing to 8 no. external window sills (W1-W8).

ORIGINAL TRUSTMARK DEFECT PHOTOGRAPHS



REMEDIAL WORKS CARRIED OUT

End caps fitted to the external window sills.

WINDOW 1 - BEFORE REMEDIATION



WINDOW 1 - COMPLETED WORK



WINDOW 2 - COMPLETED WORK



WINDOW 3 - COMPLETED WORK



WINDOW 4 - COMPLETED WORK



WINDOW 5 - COMPLETED WORK



WINDOW 6 - COMPLETED WORK

