just now - Edit - Delete

☐ Latch on light well exit door				
i	n list <u>In Progress</u>			
	Labels			
	maintenance	health, safety, fire		
	Description Ed	<u>it</u>		
	There is a latch on the gate the fire inspector pointed out. It needs to be removed.			
Paint with remaining hammerite				
	Attacimients			
		trello2108482156.jpg 🖸 Added a minute ago - Comment - Delete		
		Remove Cover		
		INO 00470040 400000 in a 57		
		IMG_20170912_183633.jpg ☐ Added 12 Sep at 18:56 - <u>Comment</u> - <u>Delet</u>	<u>e</u>	
		■ Make Cover		
	Add an attachment			
: =	Activity			Hide Details
-				
PL	Philip Lourandos			
	Removed ba	rrel latch with angle grinder this morning		

1 of 3 2017-09-23, 11:01

Philip Lourandos attached $\underline{\text{trello2108482156.jpg}}$ to this card



a minute ago - Reply

PL Philip Lourandos moved this card from Backlog to In Progress 3 hours ago

Philip Lourandos

Work colleague will lone some tools for me to remove this

15 Sep at 07:37 - Edit - Delete

2 of 3 2017-09-23, 11:01

PL Philip Lourandos attached IMG 20170912 183633.jpg to this card



12 Sep at 18:56 - Reply

Philip Lourandos

I've asked the trustees if anyone has a dremel rotary tool so I can remove it

12 Sep at 16:44 - Edit - Delete

PL Philip Lourandos added this card to Backlog 12 Sep at 16:43

3 of 3 2017-09-23, 11:01