NAME	DONALD CANNING		(3)	Original I	- 1	WRITT	TEN BY	PO#		1 2	1 9	9	(1)
EMAIL		PHON 8-33	VE 76852		STIMATE 1		DATE	TIME	PERSON	N CONTACTED	BY WHOM	1	Y PHONE PERSON
ADDRESS ENG Odo NZ et G S 4					PHONE REASON						<u></u>	ADDITIONAL FEE	
Year 2006	Make	Model GTO	Trim/Note	REVISED E	STIMATE 2		DATE	TIME	PERSO	ON CONTACTED	BY WHOM	l .	BY PHONE N PERSON
VIN	-		ATB558	PHONE			REASON			-		ADDITIC	NAL FEE
DIS_y GVWR	_n AUTO <u>(v/)</u> n TAC: R#:	PCV: V	A	TIM IR:	ING:			EVAP: \		TW	C: سر	MII	. 2
QTY	NUMBER/DESCRIPTION		AMOUNT	OP			REPAI	R ORDER INST	RUCT	IONS		SVC	CHG
					Smog 9	96 &	newer					51	
												0	
		, , , , , , , , , , , , , , , , , , ,											*
													
						<u></u>							
									, , , , , , , , , _				
									YE	LP		-7	
	SUBLET REPAIRS			your emplo	yees' permissi	on to ope	trate the vehicle h	with the necessary material, erein described on streets, h	ighways or	elsewhere for the	TOTAL SERVICE		
				purpose of removed w Automotive	testing and/or i ill be discarded : Services LJgC	nspection unless is	n. I also authorize nstructed otherwis R RAVE=\$90/HC	any sublet repair that you one. Kearny Mesa Smog Cho DUR:	leem necess eck & Repai	ary, All parts r is part of Balboa	PARTS		· · · · · · · · · · · · · · · · · · ·
				SIGN	#		<u>v</u>	>		te: 7/5/14	ENVIL FEE		
					BALBO)A AU	томотг	VE SERVICE			TAX		· · · · · · · · · · · · · · · · · · ·
	TOTAL				4191 Cor	voy S	St San D	IECK & REPAIR Piego, CA 92111 8) 874-8490	*	BAS	TOTAL	44	1,0

Smog Check Vehicle Inspection Report (VIR)

Vehicle Information

Test Date/Time: 07/05/2014 @ 10:46

Model Year: 2006

Make: State:

PONTIAC

Model:

GTO

License: 6ATB558 Engine Size: 6.0 L

Type:

CA Passenger VIN: Transmission:

6G2VX12UX6L561148 Manual

GVWR: N/A

Test Weight: N/A Certification: California Cylinders: VLT Record #: 8 33822

Odometer: 130054 Fuel Type: Gasoline

Exhaust:

Single

Inspection Reason: Biennial

Overall Test Results

Congratulations! Your vehicle passed the enhanced Smog Check inspection, which helps California reach its daily goal of removing an extra 100 tons of smog-forming emissions from the air. Thank you for keeping your vehicle well maintained.

Smog Check Certificate Number: YH446676

DMV ID Number: 4549H912Y238

Your Smog Check certificate has been electronically transmitted to DMV.

Your certificate is valid for 90 days from date of issuance.

Please keep this copy for your records.

Emission Control Systems Visual Inspection/Functional Check Results

(Visual/Functional tests are used to assist in the identification of oxides of nitrogen, crankcase and cold start emissions which are not measured during the Idle test)

<u>Result</u>	<u>ECS</u>	<u>Result</u>	<u>ECS</u>	Result	ECS
Pass	PCV	N/A	Thermostatic Air Cleaner	Pass	Fuel Evaporative Controls
Pass	Catalytic Converter	N/A	Air Injection	Pass	OBD System Checks
N/A	EGR Visual	Pass	Vacuum Lines to Sensors/	Pass	Carb./Fuel Injection
N/A	EGR Functional		Switches	Pass	Other Emission Related
N/A	Fuel Cap Functional	N/A	Ignition Timing:		Components
Pass	Fuel Cap Visual	Pass	Wiring to Sensors	Pass	Oxygen Sensor
Pass	Spark Controls	N/A	Fillpipe Restrictor	Pass	Liquid Fuel Leaks
N/A	Fuel Evaporative Controls F	unctional			

Idle Emission Test Results

		%CO ₂	%O ₂	HC (PPM)				CO (%)		
Test	RPM	MEAS	MEAS	MAX	AVE	MEAS	MAX	AVE	MEAS	Results
Idle	814	14.9	0.0	100	17	6	1.00	0.00	0.02	PASS
2500 RPM	2393	14.8	0.1	130	12	3	1.00	0.10	0.00	PASS

MAX = Maximum Allowable Emissions

AVE = Average Emissions For Passing Vehicles

MEAS = Amount Measured

Smog Check Inspection Station Information

BALBOA AUTOMOTIVE SERVICE 4191 Convoy st, San Diego, CA 92111

(858) 278-1212

Station Number: RC262198

Technician Name/Number:

GAROFALO, LOUIS/E0633743

Repair Tech Name/Number:

Software Version/EIS Number: 1301/ES519943

I certify, under penalty of perjury, under the laws of the State of California, that I performed the inspection in accordance with all bureau requirements, and that the information listed on this vehicle inspection report is true and accurate

Technician's Signature