

[illegible]

Smog Check Vehicle Inspection Report (VIR)

Vehicle Information

Test Date/Time: 05/16/2014 @ 11:24

Model Year: 2002
License: 4YLR668
Engine Size: 2.5 L
GVWR: 4123
Odometer: 127169
Fuel Type: Gasoline

Make: SUZUKI
State: CA
Type: Truck
Test Weight: N/A
Certification: California
Exhaust: Single

Model: GRAND VITARA 4WD
VIN: JS3TD62VX24160493
Transmission: Automatic
Cylinders: 6
VLT Record #: 31114
Inspection Reason: Change of Ownership

Overall Test Results

Congratulations! Your vehicle passed the enhanced Smog Check inspection, which helps California reach its daily goal of removing an extra 100 tons of smog-forming emissions from the air. Thank you for keeping your vehicle well maintained.

Smog Check Certificate Number: YF647709
DMV ID Number: **9443F948Y233**

Your Smog Check certificate has been electronically transmitted to DMV.
Your certificate is valid for 90 days from date of issuance.
Please keep this copy for your records.

Emission Control Systems Visual Inspection/Functional Check Results

(Visual/Functional tests are used to assist in the identification of oxides of nitrogen, crankcase and cold start emissions which are not measured during the Idle test)

Result	ECS	Result	ECS	Result	ECS
Pass	PCV	N/A	Thermostatic Air Cleaner	Pass	Fuel Evaporative Controls
Pass	Catalytic Converter	N/A	Air Injection	Pass	OBD System Checks
Pass	EGR Visual	Pass	Vacuum Lines to Sensors/ Switches	Pass	Carb./Fuel Injection
N/A	EGR Functional		Ignition Timing:	Pass	Other Emission Related Components
N/A	Fuel Cap Functional	N/A	Wiring to Sensors	Pass	Oxygen Sensor
Pass	Fuel Cap Visual	Pass	Fillpipe Restrictor	Pass	Liquid Fuel Leaks
Pass	Spark Controls	N/A			
N/A	Fuel Evaporative Controls Functional				

Idle Emission Test Results

Test	RPM	%CO ₂		%O ₂		HC (PPM)			CO (%)			Results
		MEAS	MEAS	MAX	AVE	MEAS	MAX	AVE	MEAS	MAX	AVE	
Idle	770	14.8	0.0	100	17	4	1.00	0.00	0.03			PASS
2500 RPM	2416	14.8	0.0	170	13	2	1.00	0.10	0.02			PASS

MAX = Maximum Allowable Emissions

AVE = Average Emissions For Passing Vehicles

MEAS = Amount Measured

Smog Check Inspection Station Information

BALBOA AUTOMOTIVE SERVICE
4191 Convoy st, San Diego, CA 92111
(858) 278-1212
Station Number: RC262198

Technician Name/Number: GAROFALO, LOUIS/EO633743
Repair Tech Name/Number:
Software Version/EIS Number: 1301/ES519943

I certify, under penalty of perjury, under the laws of the State of California, that I performed the inspection in accordance with all bureau requirements, and that the information listed on this vehicle inspection report is true and accurate.

5/16/14
Date

Technician's Signature