

[illegible]

Smog Check Vehicle Inspection Report (VIR)

Vehicle Information

Test Date/Time: 05/16/2014 @ 14:13

Model Year: 2007	Make: BMW	Model: 335i
License: 6MHK958	State: CA	VIN: WBAVB735X7KY61794
Engine Size: 3.0 L	Type: Passenger	Transmission: Automatic
GVWR: N/A	Test Weight: 3625	Cylinders: 6
Odometer: 79765	Certification: California	VLT Record #: 35233
Fuel Type: Gasoline	Exhaust: Single	Inspection Reason: Change of Ownership

Overall Test Results

Congratulations! Your vehicle passed the enhanced Smog Check inspection, which helps California reach its daily goal of removing an extra 100 tons of smog-forming emissions from the air. Thank you for keeping your vehicle well maintained.

Smog Check Certificate Number: YF647714
DMV ID Number: **9849F970Y434**

Your Smog Check certificate has been electronically transmitted to DMV.
Your certificate is valid for 90 days from date of issuance.
Please keep this copy for your records.

Emission Control Systems Visual Inspection/Functional Check Results

(Visual/Functional tests are used to assist in the identification of crankcase and cold start emissions which are not measured during the ASM test)

Result	ECS	Result	ECS	Result	ECS
Pass	PCV	N/A	Thermostatic Air Cleaner	Pass	Fuel Evaporative Controls
Pass	Catalytic Converter	N/A	Air Injection	Pass	OBD System Checks
N/A	EGR Visual	Pass	Vacuum Lines to Sensors/ Switches	Pass	Carb./Fuel Injection
N/A	EGR Functional		Ignition Timing:	Pass	Other Emission Related Components
N/A	Fuel Cap Functional	N/A	Wiring to Sensors	Pass	Oxygen Sensor
Pass	Fuel Cap Visual	Pass	Fillpipe Restrictor	Pass	Liquid Fuel Leaks
Pass	Spark Controls	N/A			
N/A	Fuel Evaporative Controls Functional				

ASM Emission Test Results

		%CO ₂	%O ₂	HC (PPM)			CO (%)			NO (PPM)			
Test	RPM	MEAS	MEAS	MAX	AVE	MEAS	MAX	AVE	MEAS	MAX	AVE	MEAS	Results
15 mph	1204	14.7	0.0	52	4	3	0.49	0.01	0.00	425	16	0	PASS
25 mph	1391	14.8	0.0	36	4	6	0.47	0.01	0.00	712	15	0	PASS

MAX = Maximum Allowable Emissions

AVE = Average Emissions For Passing Vehicles

MEAS = Amount Measured

Smog Check Inspection Station Information

BALBOA AUTOMOTIVE SERVICE
4191 Convoy st, San Diego, CA 92111
(858) 278-1212
Station Number: RC262198

Technician Name/Number: GAROFALO, LOUIS/EO633743
Repair Tech Name/Number:
Software Version/EIS Number: 1301/ES519943

I certify, under penalty of perjury, under the laws of the State of California, that I performed the inspection in accordance with all bureau requirements, and that the information listed on this vehicle inspection report is true and accurate.

Date

Technician's Signature