

Vehicle Inspection Certificate



This certificate is assigned unique code **11502** linked to **27826184424**.

Inspection completed on **08 November 2023, 12:58** by **PIERRE** using Glasfit WhatsApp Services.

Inspection Details

Name	Pierre	Inspect Type	Vehicle
Surname	Van Rensburg	Make	VOLKSWAGEN
Policy Number	891002845	Model	VW 250 - POLO
Insurer	virseker	Mobile #	27826184424

Vehicle Details

Licence #	CY415792	Colour	Blue / Blou
Registration #	GFS587K	Odometer (KM's)	131926
VIN #	AAVZZZ6RZFU050424	Disc Expiry	2024-09-30
Engine #	CJZ410192	Description	Hatch back / Luikrug

Vehicle Inspection Checks

Any visible chips on the vehicle windscreen?	No
Is your licence disk on the windscreen valid?	Yes
Do you have a valid South African Drivers Licence?	Yes
Do you have any Anti-Theft Accessories fitted to the vehicle?	Yes
Do you have an upgraded sound system installed in the vehicle?	No
Any visible damage to the *FRONT* of the vehicle?	No
Any visible damage to the *BACK* of the vehicle?	No
Any visible damage to the *LEFT* of the vehicle?	No
Any visible damage to the *RIGHT* of the vehicle?	No
Is the interior of the vehicle in a good condition?	Yes
Is the exterior of the vehicle in a good condition?	Yes

Inspection Comments

VEHICLE IN GOOD CONDITION, SMASH AND GRAB FITTED TO WINDOWS, NO VISIBLE DAMAGE.

Inspection Images

Front		Back	
Left		Right	
Windscreen		Odometer	
Licence Disc		Driver's Licence	

Declaration

I understand and accept that the findings in this inspection report are true and accurate. I confirm that the content of the inspection report includes any and / or all vehicle accessories as at the time of the inspection being completed.

Accepted by **Pierre Van Rensburg** on **08 November 2023, 12:58**.