


BYZANTINE ARCHITECTURE IN ALBANIA

GREAT BASILICA OF BUTRINT




BASILICA IN BYLIS




BASILICA IN BYLIS




BASILICA IN ARAPAJ, DURRËS



THE CHURCH OF LIN (NEAR POGRADEEC)



BAPTISTRY OF BUTRINT




BAPTISTERY OF BUTRINT




THE BASILIKAL TYPE

CHURCH OF ST. NICHOLAS IN PERONDI NEAR BERAT



DOMED CROSS-IN-SQUARE TYPOLOGY THE TRANSITIONAL VARIANT

1. CHURCH OF ST. MARY IN UPPER PESHKOPI (GJIROKASTËR)




DOMED CROSS-IN-SQUARE TYPOLOGY




THE TRANSITIONAL VARIANT

2. CHURCH OF ST. MARY IN KOSINA (PËRMET)



DOMED CROSS-IN-SQUARE TYPOLOGY THE CRYSTALLIZED VARIANT


THE HOLY TRINITY IN
THE CASTLE OF BERAT



DOMED CROSS-IN-SQUARE TYPOLOGY
THE COMPOSITE VARIANT
THE MONASTERY OF ST. MARY, APOLLONIA





CHURCH OF ST. MARY, APOLLONIA



DOMED CROSS-IN-SQUARE TYPOLOGY THE VARIANT WITHOUT INTERNAL SUPPORTS


1. CHURCH OF ST. MICHAEL, BERAT
2. CHURCH OF CHRIST IN MBORJE
NEAR KORÇA




FREE CROSS-PLAN CHURCHES ST. MARY'S MONASTERY ON THE ISLAND OF ZVĚRNEC



CHURCH OF MARMIROI





CHURCH OF ST. MARY'S MONASTERY OF ZVĚRNEC





CHURCHES WITH UNIQUE SOLUTIONS

CHURCH OF ST. MARY IN LABOVA E KRYQIT



CHURCH OF ST. NICHOLAS MONASTERY IN MESOPOTAM




**CONSOLIDATION AND RESTORATION OF THE
CHURCH OF THE NATIVITY OF ST. MARY
IN LABOVË E KRYQIT – GJIROKASTËR**

THE STATE BEFORE RESTORATION



THE COMPOSITION OF THE INTERIOR SPACE


THE FLOOR PLAN WITH THE PHASES OF CONSTRUCTION




THE DECORATIVE ARCADES DIVIDING THE ARMS OF THE CROSS



THE ICONOSTASIS (1805)




THE VOLUMETRIC COMPOSITION OF THE EXTERIOR



THE RECONSTRUCTION OF THE EASTERN FAÇADE, 1776



RECONSTRUCTIONS AND REINFORCEMENTS OF THE YEAR 1776




THE DAMAGES TO THE STRUCTURE



THE DAMAGES TO THE STRUCTURE





THE CONSTRUCTIVE SCHEME





THE SUPPORTING ARCHES OF THE DOME



THE CONSTRUCTIVE SCHEME OF THE CENTRAL SPACE



THE CONTROL OF THE DOME'S INCLINATION GEOLOGICAL SURVEYS



WORKS FOR THE CONSOLIDATION OF THE STRUCTURES




THE DISCOVERY OF THE ORIGINAL ROOF TILES



MBULIMI ME TJEGULLA




THE UNCOVERING OF THE EASTERN FAÇADE



THE UNCOVERING OF THE EASTERN FAÇADE




THE UNCOVERING OF THE WESTERN FAÇADE



THE UNCOVERING OF THE NORTHERN FAÇADE



THE RESTORATION OF THE DECORATION



THE MONUMENT AFTER RESTORATION



THE MONUMENT AFTER RESTORATION





**RESTORATION OF THE CHURCH OF ST.
MARY IN PESHKËPI E SIPËRME,
GJIROKASTËR**

THE POSITION OF THE CHURCH IN THE DROPULL VALLEY



THE CHURCH OF ST. MARY: FLOOR PLAN, AXONOMETRIC SECTION, EASTERN VIEW AND SYNTHRONON



CARVED STONE ELEMENTS FROM EARLIER PERIODS







THE DECORATIVE
TREATMENT OF THE
ADDITION ON THE
SOUTHERN SIDE



THE CONDITION OF THE MONUMENT BEFORE RESTORATION



● Reinforcements



CRACKS IN CURVED STRUCTURES





CRACKS IN CURVED STRUCTURES



CRACKS IN THE APSES



CRACKS IN MASONRY




THE GROWTH OF TREES INSIDE THE CHURCH



IMPORTANT ELEMENTS DISCOVERED DURING RESTORATION

SECTION A-A



A



B



A



1 A. TRACES OF THE CORNICES
OF THE ROOFS OF THE CORNER
SPACES ON THE EASTERN WALL
B. TRACES OF THE ROOF LEVELS
OF THE NORTHEASTERN
CORNER SPACE



A

2 A. TRACES OF THE GUTTER
BETWEEN THE ROOFS OF THE
CORNER SPACES AND THE
DOUBLE-PITCHED ROOFS OF
THE SOUTHERN ADDITION
(SECOND CONSTRUCTION
PHASE OF THE CHURCH)

2 B. TRACES OF THE GUTTER
OUTLET ON THE EASTERN WALL



A



B


TRACES OF THE TILES FROM THE ORIGINAL ROOF COVERING




TRACES OF THE TILES FROM THE ORIGINAL ROOF COVERING




THE EASTERN FAÇADE PROPOSAL




WESTERN FAÇADE PROPOSAL



SOUTHERN FAÇADE P ROPOSAL



CONSOLIDATION INTERVENTION



THE MONUMENT AFTER RESTORATION

EASTERN FAÇADE



THE MONUMENT AFTER RESTORATION THE EASTERN FAÇADE OF THE SOUTHERN ADDITION



THE MONUMENT AFTER RESTORATION WESTERN FAÇADE



THE MONUMENT BEFORE AND AFTER RESTORATION

