

Lic. No. : SLA-34369/2025-2028.
Expiry on: : 27-11-2028.
IISLA No. : F/W/00200
E-mail : vikram.dhule9@gmail.com
CELL : 9518510366, 9423662250

MOTOR,MARINE,ENGG
62, Vighnaharta Colony,
Near Aakshwani, Deopur,
Dhule- 424005.

REINSPECTION REPORT

Ref No. : RIN/416/2026

Date : 01/04/2026

INSURANCE POLICY PARTICULARS

Insurer's Name : United India Insurance Co. Ltd
Policy issuing office : 230106 BRDIV
Address : 230106 BRDIV MAHADULE BUILDING, FLOORNO -2 OPP INDIAN OIL
PETROL PUMP, MEDICAL SQUARE, NAGPUR MAHARASHTRA
Insured Name : PRASHANT GANAPAT PAWARA
Insured's Address : AT SABLAPANI POST RANIPUR, TAL SHAHADA, DIST NANDURBAR,
Nandurbar, MH, 425409
Policy Number : 2301063125P106698414
Claim No : 2301063125C050116001/1
Policy Period : 26/07/2025 To 25/07/2026
Vehicle Finance Details : MMFSL

DETAILS OF SURVEY

Date of Accident : 19/01/2026
Time of Accident : AND SUBSEQUENT VISITS.
Date Of Reinspection : 20/03/2026
Place of Survey : Aakash Automotives,Awdhan,Dhule.

VEHICLE PARTICULAR

Registration Number : MH.39.AD.2416
Class of Vehicle : LGV GOODS CARRIER
Make of Vehicle : Mahindra & Mahindra
Model of Vehicle : Bolero MAXX PUP HD 1.7 LX
Chassis Number : MA1RA2TTKP1L93420
Engine Number : TTP1L67218
Odometer : 35191 km

WE HAVE RE-INSPECTED THE CAPTIONED VEHICLE & HAVE FOUND THAT THE REPAIRS /OR & REPLACEMENTS MADE THERE IN WERE STRICTLY FOLLOWED AS PER OUR FINAL SURVEY REPORT BEARING REF NO MOTOR-828/2026 DATE. 01-04-2026. I HAVE INSPECTED THE SAID VEHICLE & HAVE TAKEN A FEW NECESSARY PHOTOGRAPHS OF THE SAME ALONG WITH THE SALVAGE PARTS.THE VEHICLE RE-INSPECTED WAS FOUND TO BE IN ROAD WORTHY CONDITION AT THE TIME OF MY SURVEY.



Vikram Patil

VIKRAM PATIL

R.I PHOTOS & MY BILL FOR SURVEY.