**WATANABE HEAT TREATMENT CO.,LTD**

# INSPECTION REPORT OF HEAT TREATMENT

Issue Date 20/02/2026

| Wos No. | Approval | Charge |
|---|---|---|
| 0633287-00 | | |

| Customer Name | Treatment type | Material |
|---|---|---|
| SRIBORISUTH INDUSTRIAL CO., LTD. | NORMALIZING | S35C |

| P/O No. or Manufacturing No. | Customer lot no. | Quantity | Heat Treatment Lot No. | Inspection Date |
|---|---|---|---|---|
| 780/38986 | 1309/C7147/110269(TANK 5) | 1148 | M05-26-0254 | 19/02/2026 |

| Parts Code | Drawing No. | Parts Name |
|---|---|---|
| 110320 | 26121-52F-0000-001J(W13-09) | HUB,TC PUMP |

| Inspection Item | | Specification | LowerLimit | UpperLimit | Measurement result |
|---|---|---|---|---|---|
| SURFACE HARDNESS | 1 | HRB | 83 | 95 | 88.5 |
| | 2 | HRB | 83 | 95 | 89.8 |
| | 3 | HRB | 83 | 95 | 89.1 |

Measurement Point

Surface Hardness Check Point

PASS
23 / 02 / 69
ผู้ตรวจสอบ.....
หัวหน้าแผนก.....

Note

Judgement: OK

Customer

| Approved | Checked by | Issued by |
|---|---|---|
| Date : | Date : | Date : |