



FIELD SERVICE REPORT

Doc No. - QF/DPS/315
RevNo. - 02
Dated - 01-01-1970.
(Installation Certificate/Service Report)

SITE DETAILS

Site ID UEGT13013 Circle : UP EAST
Site Name BASOB
Site Address JALAUN
(25.9040031-79.259739)

CUSTOMER DETAILS

Key Cont. Name : MOHAMMAD Customer BHARTI INFRATEL
SAYEED LIMITED
Email Id Mobile 9839735323

COMPLAINT DESCRIPTION : pm/cm lvd card fault

AC INPUT : R-Y Y-B B-R DC Voltage 53.55
000 225 000

V(E-N) 0.0 DC Load : 109

SPD Status ok Temperature 38.6

BATTERY DETAILS

Make/AH/Type: 1200 ah Exide, HBL
V (Batt) :53.55 V (FL) :54.4 V (boost) : 55.2
LLVD Set Voltage : 44 BLVD Set Voltage : 42

SYSTEM DETAILS

Sr. No. : 23R1639C1004811940
Product FG Code : DISMJA7GSI-005-S
Model/Rating & Qty : SMCS
Rectifier Rating & Qty : 04
Configuration ☒ Single ☐ Parallel ☐ Hot Standby
Installation Date N/A

FSR No. 19I632070-2
Call Type

Date: 20-10-2019
☐ Installation ☐
Breakdown ☒ PM ☐ ECN ☐
Retrofit
☐ Warranty ☒ AMC ☐
Chargeable ☐ Others

Service Type

Engineer : Shailendra Singh
Delta Complaint No. 19I632070

Customer Complaint No. NA

Log Date 14-09-2019 Time 15:38

Attend Date 20-10-2019 Time 15:15

Close Date 20-10-2019 Time 15:28

Status

CLOSED ☐		OPEN ☐		PENDING ☐		BROKEN ☒	
Sr.No	DESCRIPTION	Yes	No	N/A			
1	Physical Inspection	☒	☐	☐			
2	Cleaning of System	☒	☐	☐			
3	Verifying the Tightness of all Control and Power Connections	☒	☐	☐			
4	Control and Power Connections	☒	☐	☐			
5	Functioning and Direction of Rotation of Cooling Fan	☐	☐	☒			
6	Power and Communications of all Addon Cards	☒	☐	☐			
7	Modem/Pushpak Functioning & Communication with NOC	☒	☐	☐			
8	DG Battery Charging	☒	☐	☐			
9	Class C/B SPD Status	☒	☐	☐			
10	Check the DC Bus for Heat discoloration	☒	☐	☐			
11	Check the all Existing Alarm	☒	☐	☐			
12	Others	☒	☐	☐			

Spare Part Code	Part Name	Faulty Sr. No.	Fault Description	Replaced Sr. No.	Quantity
Not Applicable	Not Applicable	Not Applicable	NA	NA	0

ACTION TAKEN FOR FAULT RECTIFICATION

site visit load lvd faulty system not OK

ROOT CAUSE ANALYSIS (May Include relevant pictures of System, Faulty area, faulty parts analysis & Preventive Measures)

call broken


Shailendra Singh/7247552929
Delta Engineer's & Signature/Contact No.

Customer Remarks

C-SAT

Poor Fair Satisfactory Very Good Excellent
☒ ☐ ☐ ☐ ☐


Customer Signature & Stamp/Contact No.

Gurgaon : +91-124-4169040
Hyderabad : +91-124-4169040

GSM : +91-124-4169040
Mumbai : +91-124-4169040

Bangalore : +91-124-4169040
Kolkata : +91-124-4169040

Central HelpDesk No : 24 x 7
Toll Free : 18001036333 and
18002663300

This is Computer generated FSR