

# Infrastructure Crack Detection Report

Report Date:	2026-02-08 21:56:42
Image File:	00070.jpg
Analysis Status:	Complete

## Detection Result

**CRACK DETECTED**

Confidence: 54.19%

## Severity Analysis


Severity Level:	MEDIUM
Severity Score:	53.6/100
Affected Area:	8.41%
Estimated Length:	200.8 pixels
Estimated Width:	48.5 pixels
Recommendation:	Schedule inspection. Potential structural concern.

## Visual Analysis

Original Image:



**Crack Heatmap:**



**Detected Crack Location:**



*Disclaimer: This report is generated by an AI-powered crack detection system and should be used for preliminary assessment only. Professional structural engineering inspection is recommended for critical infrastructure decisions.*