

AIRCRAFT INSPECTION REPORT

Borrower:

Lender: US Aviation Finance, LLC
65 Millet Street #103
Richmond, VT 05477

DESCRIPTION OF AIRCRAFT	FAA NUMBER
2006 MOONEY M20M SN: 27-0353	N 69MB

EXTERIOR CONDITION	SPECIAL EQUIPMENT																																																																																																
<table style="width: 100%;"> <tr> <th></th> <th>Good</th> <th>Avg.</th> <th>Poor</th> </tr> <tr><td>a. Tires</td><td>☒</td><td>☐</td><td>☐</td></tr> <tr><td>b. Gear</td><td>☒</td><td>☐</td><td>☐</td></tr> <tr><td>c. Struts</td><td>☒</td><td>☐</td><td>☐</td></tr> <tr><td>d. Cowling</td><td>☒</td><td>☐</td><td>☐</td></tr> <tr><td>e. Prop</td><td>☒</td><td>☐</td><td>☐</td></tr> <tr><td>f. Glass</td><td>☒</td><td>☐</td><td>☐</td></tr> <tr><td>g. Covering/Skin</td><td>☒</td><td>☐</td><td>☐</td></tr> <tr><td>h. Control Surfaces</td><td>☒</td><td>☐</td><td>☐</td></tr> <tr><td>i. Flaps</td><td>☒</td><td>☐</td><td>☐</td></tr> <tr><td>j. Lights</td><td>☒</td><td>☐</td><td>☐</td></tr> <tr><td>k. Antenna</td><td>☒</td><td>☐</td><td>☐</td></tr> </table>		Good	Avg.	Poor	a. Tires	☒	☐	☐	b. Gear	☒	☐	☐	c. Struts	☒	☐	☐	d. Cowling	☒	☐	☐	e. Prop	☒	☐	☐	f. Glass	☒	☐	☐	g. Covering/Skin	☒	☐	☐	h. Control Surfaces	☒	☐	☐	i. Flaps	☒	☐	☐	j. Lights	☒	☐	☐	k. Antenna	☒	☐	☐	<table style="width: 100%;"> <tr> <th>Description:</th> <th>Good</th> <th>Avg.</th> <th>Poor</th> </tr> <tr><td>a.</td><td>☐</td><td>☐</td><td>☐</td></tr> <tr><td>b.</td><td>☐</td><td>☐</td><td>☐</td></tr> <tr><td>c.</td><td>☐</td><td>☐</td><td>☐</td></tr> <tr><td>d.</td><td>☐</td><td>☐</td><td>☐</td></tr> <tr><td>e.</td><td>☐</td><td>☐</td><td>☐</td></tr> <tr><td>f.</td><td>☐</td><td>☐</td><td>☐</td></tr> <tr><td>g.</td><td>☐</td><td>☐</td><td>☐</td></tr> <tr><td>h.</td><td>☐</td><td>☐</td><td>☐</td></tr> <tr><td>i.</td><td>☐</td><td>☐</td><td>☐</td></tr> <tr><td>j.</td><td>☐</td><td>☐</td><td>☐</td></tr> <tr><td>k.</td><td>☐</td><td>☐</td><td>☐</td></tr> </table>	Description:	Good	Avg.	Poor	a.	☐	☐	☐	b.	☐	☐	☐	c.	☐	☐	☐	d.	☐	☐	☐	e.	☐	☐	☐	f.	☐	☐	☐	g.	☐	☐	☐	h.	☐	☐	☐	i.	☐	☐	☐	j.	☐	☐	☐	k.	☐	☐	☐
	Good	Avg.	Poor																																																																																														
a. Tires	☒	☐	☐																																																																																														
b. Gear	☒	☐	☐																																																																																														
c. Struts	☒	☐	☐																																																																																														
d. Cowling	☒	☐	☐																																																																																														
e. Prop	☒	☐	☐																																																																																														
f. Glass	☒	☐	☐																																																																																														
g. Covering/Skin	☒	☐	☐																																																																																														
h. Control Surfaces	☒	☐	☐																																																																																														
i. Flaps	☒	☐	☐																																																																																														
j. Lights	☒	☐	☐																																																																																														
k. Antenna	☒	☐	☐																																																																																														
Description:	Good	Avg.	Poor																																																																																														
a.	☐	☐	☐																																																																																														
b.	☐	☐	☐																																																																																														
c.	☐	☐	☐																																																																																														
d.	☐	☐	☐																																																																																														
e.	☐	☐	☐																																																																																														
f.	☐	☐	☐																																																																																														
g.	☐	☐	☐																																																																																														
h.	☐	☐	☐																																																																																														
i.	☐	☐	☐																																																																																														
j.	☐	☐	☐																																																																																														
k.	☐	☐	☐																																																																																														

INTERIOR	INSTRUMENTS																																
<table style="width: 100%;"> <tr> <th></th> <th>Good</th> <th>Avg.</th> <th>Poor</th> </tr> <tr><td>a. Upholstery</td><td>☒</td><td>☐</td><td>☐</td></tr> <tr><td>b. Headliner</td><td>☒</td><td>☐</td><td>☐</td></tr> <tr><td>c. Baggage Compartment</td><td>☒</td><td>☐</td><td>☐</td></tr> <tr><td>d. Carpeting</td><td>☒</td><td>☐</td><td>☐</td></tr> <tr><td>e. Interior Lights</td><td>☒</td><td>☐</td><td>☐</td></tr> </table>		Good	Avg.	Poor	a. Upholstery	☒	☐	☐	b. Headliner	☒	☐	☐	c. Baggage Compartment	☒	☐	☐	d. Carpeting	☒	☐	☐	e. Interior Lights	☒	☐	☐	Current Total Tachometer Hours: <u>HOBAS METER 907.0</u> Optional Equipment Installed: <table style="width: 100%;"> <tr> <td>☐ Rate of Climb</td> <td>☐ Clock</td> </tr> <tr> <td>☐ Turn Coordinator</td> <td>☐ Cylinder Head Temperature</td> </tr> <tr> <td>☒ Attitude Indicator</td> <td>☐ Exhaust Gas Temperature</td> </tr> <tr> <td>☐ Directional Gyro</td> <td>☒ Other: <u>Airspeed, Altimeter</u></td> </tr> </table>	☐ Rate of Climb	☐ Clock	☐ Turn Coordinator	☐ Cylinder Head Temperature	☒ Attitude Indicator	☐ Exhaust Gas Temperature	☐ Directional Gyro	☒ Other: <u>Airspeed, Altimeter</u>
	Good	Avg.	Poor																														
a. Upholstery	☒	☐	☐																														
b. Headliner	☒	☐	☐																														
c. Baggage Compartment	☒	☐	☐																														
d. Carpeting	☒	☐	☐																														
e. Interior Lights	☒	☐	☐																														
☐ Rate of Climb	☐ Clock																																
☐ Turn Coordinator	☐ Cylinder Head Temperature																																
☒ Attitude Indicator	☐ Exhaust Gas Temperature																																
☐ Directional Gyro	☒ Other: <u>Airspeed, Altimeter</u>																																

EQUIPMENT	Brand Name	Model No.
Nav 1:	<u>GARMIN</u>	<u>G1000</u>
Com 1:		
Nav 2:		
Com 2:		
Transponder:	<u>GARMIN</u>	
ADF:		
Loran/GPS:		

LOG BOOKS	Serial No.	Model No.	Total Time	Time from Overhaul
Airframe	<u>27-0353</u>	<u>M20M</u>	<u>907</u>	
Engine No. 1	<u>L-12240-61A</u>	<u>T10-540-AF1B</u>	<u>907</u>	<u>893</u>
Engine No. 2				

IS AIRCRAFT AIRWORTHY? ☒ YES ☐ NO

IF NOT, WHY?

GENERAL COMMENTS

WHERE WILL AIRCRAFT BE HANGARED OR KEPT?

ANY OUTSTANDING FAA AIRWORTHINESS DIRECTIVES?

DANIEL GUARANDI 3734411
INSPECTED BY/PRINTED NAME A&P CERTIFICATE NUMBER

DLMM 941-800-2135 3/1/2024
SIGNATURE PHONE NUMBER DATE