

Uniform Residential Appraisal Report

 Loan#185675119
 File # 161108484

The purpose of this summary appraisal report is to provide the lender/client with an accurate, and adequately supported, opinion of the market value of the subject property.

Property Address	76 E Westland St	City	Tucson	State	AZ	Zip Code	85711
Borrower	Philips, Alex	Owner of Public Record	Philips, Alex Cp/Rs	County	Pima		
Legal Description	Del Monte Village Lot 270						
Assessor's Parcel #	128-12-2720	Tax Year	2016	R.E. Taxes \$	1,231		
Neighborhood Name	Del Monte Village	Map Reference	14S 14E Sec14	Census Tract	0035.02		
Occupant	☒ Owner ☐ Tenant ☐ Vacant	Special Assessments \$	0	PUD	☐	HOA \$	0
Property Rights Appraised	☒ Fee Simple ☐ Leasehold ☐ Other (describe)						
Assignment Type	☐ Purchase Transaction ☒ Refinance Transaction ☐ Other (describe)						
Lender/Client	Fairway Independent Mortgage Corp.	Address	5151 E. Broadway Blvd., Tucson, AZ 85711				
Is the subject property currently offered for sale or has it been offered for sale in the twelve months prior to the effective date of this appraisal? ☐ Yes ☒ No							
Report data source(s) used, offering price(s), and date(s). Research of the public records and mlssaz revealed that the subject property is not under current agreement or option and is not offered for sale and has not been offered for sale on the open market during the past 12 months.							
I ☐ did ☐ did not analyze the contract for sale for the subject purchase transaction. Explain the results of the analysis of the contract for sale or why the analysis was not performed.							

Contract Price \$	Date of Contract	Is the property seller the owner of public record?	☐ Yes ☐ No	Data Source(s)
Is there any financial assistance (loan charges, sale concessions, gift or downpayment assistance, etc.) to be paid by any party on behalf of the borrower? ☐ Yes ☐ No				
If Yes, report the total dollar amount and describe the items to be paid.				

Note: Race and the racial composition of the neighborhood are not appraisal factors.

Neighborhood Characteristics			One-Unit Housing Trends			One-Unit Housing		Present Land Use %	
Location	☒ Urban ☐ Suburban ☐ Rural	Property Values	☒ Increasing ☐ Stable ☐ Declining	PRICE	AGE	One-Unit	84 %		
Built-Up	☒ Over 75% ☐ 25-75% ☐ Under 25%	Demand/Supply	☐ Shortage ☒ In Balance ☐ Over Supply	\$ (000)	(yrs)	2-4 Unit	1 %		
Growth	☐ Rapid ☒ Stable ☐ Slow	Marketing Time	☒ Under 3 mths ☐ 3-6 mths ☐ Over 6 mths	50	Low	30	Multi-Family	1 %	
Neighborhood Boundaries	Broadway Blvd. north, Craycroft Rd. east, 22nd St. south and Columbus Blvd. west.			360	High	75	Commercial	10 %	
				150	Pred.	55	Other	4 %	

Neighborhood Description The subject property is located in the Del Monte Village subdivision in central Tucson. The neighborhood has generally average to good overall appeal with no adverse influences affecting appeal or marketability. Schools, shopping and employment are within a convenient distance. There is average to good proximity to main thoroughfares.

Market Conditions (including support for the above conclusions) Market data indicates fairly stable property values, marketing times in most markets less than 90 days, with supply and demand in balance. Seller concessions of 3% - 3.5% are typical in most markets, but less common in upper end properties and cash transactions.

Dimensions	80x151.13	Area	12090 sf	Shape	Rectangular	View	N;Res;
Specific Zoning Classification	R-1	Zoning Description	Residential				
Zoning Compliance	☒ Legal ☐ Legal Nonconforming (Grandfathered Use) ☐ No Zoning ☐ Illegal (describe)	*4% vacant land/parks/houseofworship/schools					
Is the highest and best use of subject property as improved (or as proposed per plans and specifications) the present use? ☒ Yes ☐ No If No, describe							

Utilities	Public	Other (describe)	Public	Other (describe)	Off-site Improvements - Type	Public	Private
Electricity	☒		Water	☒	Street	Asphalt	☒
Gas	☒		Sanitary Sewer	☒	Alley	Yes	☒

FEMA Special Flood Hazard Area ☐ Yes ☒ No FEMA Flood Zone X FEMA Map # 04019C2284L FEMA Map Date 06/16/2011

Are the utilities and off-site improvements typical for the market area? ☒ Yes ☐ No If No, describe

Are there any adverse site conditions or external factors (easements, encroachments, environmental conditions, land uses, etc.)? ☐ Yes ☒ No If Yes, describe

The appraiser has not checked the land records for recorded easements and has reported only apparent easements, encroachments and other apparent adverse conditions. Utility and municipal easements are typical and do not affect marketability.

General Description		Foundation		Exterior Description		materials/condition		Interior		materials/condition	
Units	☒ One ☐ One with Accessory Unit	☒ Concrete Slab ☐ Crawl Space		Foundation Walls	Concrete/Avg	Floors	Cpt, Ct/Good				
# of Stories	1	☐ Full Basement ☐ Partial Basement		Exterior Walls	Brick/Avg	Walls	Drywall/Good				
Type	☒ Det. ☐ Att. ☐ S-Det./End Unit	Basement Area	0 sq.ft.	Roof Surface	Shingle/Avg	Trim/Finish	Wood/Good				
☒ Existing ☐ Proposed ☐ Under Const.		Basement Finish	0 %	Gutters & Downspouts	Overhang/Avg	Bath Floor	Ct/Good				
Design (Style)	Ranch	☐ Outside Entry/Exit ☐ Sump Pump		Window Type	DualPane/New	Bath Wainscot	Ct/Good				
Year Built	1952	Evidence of ☐ Infestation		Storm Sash/Insulated	None/Typical	Car Storage	☒ None				
Effective Age (Yrs)	18	☐ Dampness ☐ Settlement		Screens	Metal/Avg	Driveway	# of Cars	0			
Attic	☐ None	Heating ☒ FWA ☐ HWBB ☐ Radiant		Amenities	☐ Woodstove(s) # 0	Driveway Surface	Gravel				
☐ Drop Stair ☐ Stairs		☐ Other Fuel Gas		Fireplace(s) #	0	Fence	ChnLnk	☐			
☐ Floor ☒ Scuttle		Cooling ☒ Central Air Conditioning		☒ Patio/Deck Cov	☒ Porch Uncov	Garage	# of Cars	0			
☐ Finished ☐ Heated		☐ Individual ☐ Other		☐ Pool None	☐ Other None	Carport	# of Cars	0			

Appliances ☐ Refrigerator ☒ Range/Oven ☒ Dishwasher ☒ Disposal ☐ Microwave ☐ Washer/Dryer ☒ Other (describe) Fan/Hood

Finished area above grade contains: 7 Rooms 3 Bedrooms 2.0 Bath(s) 1,522 Square Feet of Gross Living Area Above Grade

Additional features (special energy efficient items, etc.). See URAR page 3 of 6 for a list of features.

Describe the condition of the property (including needed repairs, deterioration, renovations, remodeling, etc.). C3;Kitchen-remodeled-timeframe unknown;Bathrooms-remodeled-timeframe unknown;Typical depreciation for age & quality. No functional obsolescence noted that would have an effect on value. The family room and dining room are additions that have been completed in a workmanlike manner, are heated and cooled, flow well with the original floorplan and are included in the gross living area. A copy of the permit has been scanned into this report. Subject is in overall good condition. The utilities were on and in working order at the time of inspection.

Are there any physical deficiencies or adverse conditions that affect the livability, soundness, or structural integrity of the property? ☐ Yes ☒ No If Yes, describe

There is no measurable functional or external obsolescence.

Does the property generally conform to the neighborhood (functional utility, style, condition, use, construction, etc.)? ☒ Yes ☐ No If No, describe