



16918 Rolling Acres Dr. Humble, TX. 77396 | 281-802-0247 | www.adinspections.com

Certificate of Inspection

This is to certify that the property of

James Anderson

located at

ELACHI, S.N. GHOSH AVENUE, P.O. NARENDRAPUR, DISTRICT- SOUTH 24 PARGANAS

has been inspected for compliance with the International Energy Conservation Code (IECC 5432) and meets the requirements for a Final Energy Inspection.

Report #987654 | Date of Inspection: 2026-07-12

AREAS INSPECTED & PASSED

Wall insulation · Air sealing / infiltration · Duct testing · Window U-factor / SHGC

James Southerland

Certified Energy Inspector

ICC Residential Combination Inspector · IECC Certified · License #0882584