



भारतीय तटरक्षक
Indian Coast Guard

Emergency Party Board

HEP · SSEP — Firefighting & Damage Control

Harbour Emergency Party — Firefighting Report

OPV Vighraha · Exercise · Ship in Harbour · Generated 28 Sept 2026, 18:45

SHIP OPV Vighraha	SCENARIO Ship in Harbour (Alongside)	EMERGENCY PARTY HEP — Harbour Emergency Party	INCIDENT TYPE Firefighting	LOCATION OF FIRE Galley	ASSESSMENT Minor fire — closed by Attack parties
DATE 28 Sept 2026	START TIME 1801 hrs	END TIME 1823 hrs	TOTAL DURATION 22 min	OFFICER OF THE DAY Demo Officer 1	HANDS DEPLOYED 4 of 4 billets
DRILL MODE Practice Drill	SESSION 6A647Z · Closed				

First Report — Attack Party & Attack ‘BA’ · 1805 hrs

Attack Party / Search Party

Nvk Demo Hand 02, P/Nvk Demo Hand 03 · 1802 hrs – 1823 hrs

Seat of fire at the galley range hood. First attack with 2 × CO2; flames knocked down within 3 minutes.

Attack ‘BA’ / Repair Party

L/Nvk Demo Hand 04, Yantrik Demo Hand 05 · 1803 hrs – 1822 hrs

BA team of two entered via the starboard door; hood ducting checked with thermal camera — no extension.

ASSESSMENT

MINOR FIRE

Dealt with by the Attack Party and Attack ‘BA’ — no other parties deployed.

Deployed Parties — Remarks

No other parties deployed — incident closed by the Attack parties.

Closing Remarks

Minor fire at the galley range reported by the duty cook. Attack Party and Attack 'BA' closed up within 2 minutes and extinguished the fire with 2 × CO2. Galley ventilated and declared safe. Range hood filters to be cleaned and inspected before next use.
No casualties.


Demo Officer 1

Officer of the Day

Executive Officer

Commanding Officer

Annex A — Organisation as Deployed



Note: Attack Party and Attack 'BA' are to regroup and provide assistance to Support 'A'.

Annex B — Nominal Roll / Muster Card

✓	BILLET	NAME	TIME IN	TIME OUT	PERSONAL REMARKS
OOD — Officer of the Day					
	OOD	Lt Demo Officer 1	1801 hrs	1823 hrs	
Attack Party / Search Party — 02 Jr. Nvks (ME – 01, P – 01)					
	Party remarks: Seat of fire at the galley range hood. First attack with 2 × CO2; flames knocked down within 3 minutes. — Demo Hand 02				
✓	ME	Nvk Demo Hand 02	1802 hrs	1823 hrs	Used 2 × CO2 extinguishers; visibility poor near the deckhead.
✓	P	P/Nvk Demo Hand 03	1802 hrs	1823 hrs	Carried the thermal imaging camera; reported hot spots to the BA controller.
Attack 'BA' / Repair Party — 02 Jr Nvks (QA/RP – 02)					
	Party remarks: BA team of two entered via the starboard door; hood ducting checked with thermal camera — no extension. — Demo Hand 04				
✓	QA/RP	L/Nvk Demo Hand 04	1803 hrs	1822 hrs	Ran out 2 lengths of 45 mm hose; nozzle on spray.
✓	QA/RP	Yantrik Demo Hand 05	1803 hrs	1822 hrs	Checked the boundary every 5 minutes and reported to containment.
<i>Not deployed (minor fire): Main Group · BA Controller · Support 'A' / Pumping & De-Flooding Party · Support 'B' / Shoring Party · Containment Group · Specialist Group</i>					

Annex C — Session Timeline

TIME	EVENT	BY
18:41:24	Session 6A647Z created for OPV Vighraha.	Demo Officer 1
18:41:24	Scenario: Ship in Harbour — HEP.	Demo Officer 1
18:41:24	Incident type: Firefighting.	Demo Officer 1
18:41:24	Location: Galley.	Demo Officer 1
18:41:24	VR session started — alarm raised.	Demo Officer 1
18:41:24	Attack Party entered the galley	VR
18:41:24	CO2 extinguisher discharged	VR
18:41:24	CO2 extinguisher discharged	VR
18:41:24	Fire reported out	VR
18:41:24	Demo Hand 02 marked their part complete.	Demo Hand 02
18:41:24	Demo Hand 03 marked their part complete.	Demo Hand 03
18:41:24	Demo Hand 04 marked their part complete.	Demo Hand 04
18:41:24	Demo Hand 05 marked their part complete.	Demo Hand 05
18:41:24	Attack Party report — MINOR fire.	Demo Officer 1
18:41:24	Session closed.	Demo Officer 1