

# Preliminary Vehicle Inspection Report

## General Information

Truck Serial Number: 7301234

Truck Model: 730

Inspection ID: 56748

Inspector Name: John Lauda

Inspection Employee ID: EMP001

Inspection Date & Time: 2024-08-10T14:30:00Z

Inspection Location: Warehouse A

Geo Coordinates: 40.7128,-74.0060

Service Meter Hours: 15000

Inspector Signature: JohnDoeSignature

Customer Name: Acme Corp

Customer ID: CUST12345

## Tires

Tire Pressure: Left Front: 32 PSI, Right Front: 30 PSI, Left Rear: 32 PSI, Right Rear: 30 PSI

Tire Condition: Left Front: Good, Right Front: Ok, Left Rear: Needs Replacement, Right Rear: Good

Overall Tire Summary: All tires are in good condition except the left rear which needs replacement.

Image: tire1.jpg

Image: tire2.jpg

Image: tire3.jpg

Image: tire4.jpg

## Battery

Battery Make: CAT

Battery Replacement Date: 2023-12-01T00:00:00Z

Battery Voltage: 12V

Battery Water Level: Good

Battery Condition: N

Battery Leak or Rust: N

Battery Summary: The battery is in good condition with no leaks or rust.

Image: battery1.jpg

## **Exterior**

Rust/Dent/ Damage: Y

Oil Leak in Suspension: N

Exterior Summary: There is some minor rust and a small dent on the rear bumper.

Image: exterior1.jpg

Image: exterior2.jpg

## **Brakes**

Brake Fluid Level: Ok

Brake Condition Front: Good

Brake Condition Rear: Ok

Emergency Brake: Good

Brake Summary: Brakes are in good condition overall.

Image: brakes1.jpg

## **Engine**

Rust/Dent/Damage: N

Engine Oil Condition: Good

Engine Oil Color: Clean

Brake Fluid Condition: Good

Brake Fluid Color: Clean

Oil Leak in Engine: N

Engine Summary: Engine is in good condition with no signs of rust or leaks.

Image: engine1.jpg

## **Voice of Customer**

Customer Feedback: The inspection was thorough and well documented.

Image: feedback1.jpg