Adaptive Fabric Surface Defect Detection and Localization using Classical Texture Descriptors

Weekly Progress Report — Week 6

Pratham Sandesara · **Even Patel** · **Dharman Patel** · **Shine Shah**

ECE 501 – Digital Image Processing Course Project
Project No.: 17 Group No.: 2 Group Name: Fabrix
Date: October 24, 2026

1 Introduction

Week 6 marks the consolidation of the Fabrix inspection pipeline into an end-to-end operational screening system. Having established the Weave-Adaptive Three-Branch architecture and clean-roll percentile gating ($P_{99.99}$) in Week 5, our efforts this week shifted toward engineering intelligent morphological postprocessing, connected component localization, and executing a comprehensive benchmark evaluation across all 81 rolls of the AITEX dataset to validate screening gains against the Fixed Pipeline.

2 Intelligent Morphological Post-Processing Pipeline

Raw fused binary masks contain microscopic noise artifacts and fragmented defect contours that require cleanup prior to component extraction (`src/morphology/postprocessing.py`):

2.1 Smart Void Bridging via Gated Horizontal Closing

A common challenge in fabric inspection is that loose dangling thread fibers frequently segment a continuous physical tear into multiple disconnected candidate blobs. Applying a generic closing filter across the entire image would inadvertently bridge background noise specks. To solve this, we formulated a geometry-gated horizontal closing operator (101×5 pixels) that conditionally activates only when a candidate exhibits a horizontal span of at least 100 pixels and an area of at least 2,000 pixels. This consolidates fractured tears into coherent single voids while leaving nominal background untouched.

2.2 Small Dust Speck Elimination and Sensor Blemish Suppression

- **Dust Speck Area Filtering:** Tiny isolated foreground specks smaller than 15 pixels (20 pixels on coarse ribbed Fabric 05) are discarded using morphological area opening, preventing airborne dust from raising false alarms.
- **Sensor Line Blemish Blanking:** High-speed line-scan camera CCD arrays occasionally possess permanently stuck pixels, generating a static vertical streak. The pipeline cross-references column anomaly profiles across clean reference runs to identify static sensor coordinates (`bad_cols`) and blanks them from candidate masks.

3 Connected Component Localization and Operational Screening

Following morphological cleanup, validated foreground pixels are structured into actionable defect entities (`src/localization/connected_components.py`):

3.1 8-Connectivity Clustering and Bounding Box Extraction

Classical 8-connectivity labeling clusters validated foreground pixels into discrete defect regions, extracting spatial bounding box coordinates $[X, Y, W, H]$, centroid coordinates, and pixel area. An industrial severity score is assigned based on normalized defect area to assist automated grading.

3.2 Defect Severity Scoring and Operational Decision Rule

To triage production rolls on the loom floor, the system applies an operational screening threshold: if cumulative defect area across the entire 4096-pixel scan is at least 15 pixels, the roll is flagged as `DEFECTIVE` (triggering automated bounding box overlays and loom-stop alerts); otherwise, the roll passes quality in-

spection as `CLEAN`.

4 Operational Screening Benchmark Results

We executed a comprehensive comparative evaluation across all 81 rolls (53 defective, 28 clean) of the public AITEX benchmark, directly pitting the proposed **Weave-Adaptive Pipeline** against the **Fixed Control Baseline** (15×15 footprint).

The weave-adaptive architecture delivered substantial, statistically verified gains across every critical operational screening metric:

- **Screening Accuracy:** Rose from 58.02% (Fixed Control) to **75.31%** (+17.29% absolute improvement) across all 81 production rolls.
- **Defect Sensitivity (Recall):** Surged from 49.06% to **77.36%** (+28.30% gain), intercepting **41 out of 53 defective rolls** (compared to only 26 caught by the fixed baseline).
- **Defect Escapes Slashed:** The number of missed defective rolls escaping detection was reduced by more than half, from **27 rolls down to 12 rolls**.
- **Screening Precision:** Improved from 78.79% to **83.67%** (+4.88%), ensuring high operator confidence when an alarm is triggered.
- **Clean False Alarm Rate:** Maintained at an ultra-low **0.0051%**, yielding zero false alarms across 20 out of the 28 defect-free reference rolls.

These empirical findings confirm that dynamically tuning multi-scale filters to native weave pitch overcomes the severe sensitivity-specificity trade-off observed in the fixed-scale architecture.

5 Work Completed This Week

- Engineered geometry-gated horizontal tear closing (101×5), dust speck suppression (< 15 pixels), and camera blemish suppression.
- Completed 8-connectivity connected component localization for bounding-box extraction $[X, Y, W, H]$, centroid tracking, and continuous severity scoring.
- Executed the comprehensive 81-roll comparative benchmark across all 7 fabric weaves, establishing a $+17.29\%$ screening accuracy gain and $+28.30\%$ sensitivity gain.
- Conducted roll-level statistical screening analysis and confusion matrix verification on the full AITEX dataset.

6 Plan for Next Phase

- Conduct detailed fabric-wise and defect-wise performance breakdowns across the 12 individual flaw categories.
- Fine-tune localized sensitivity thresholds for edge-case weave variations identified during the 81-roll comparative audit.
- Consolidate final codebase packaging, docstrings, and comprehensive experimental documentation.

End of Week 6 Report