

Car Damage Analysis Report

Segment: Sedan | Age: 3 yrs

DAMAGE DETECTED — SHATTER on TYRE

Detection Summary

DETECTED PART	Tyre	PART CONFIDENCE	42.5%
DAMAGE TYPE	Shatter	DAMAGE CONFIDENCE	53.7%
SEVERITY	MINOR	RISK LEVEL	High
COVERAGE	18%	REGIONS FOUND	9


AI Damage Metrics



Part Confidence & Cost Estimate



Computer Vision Analysis



Repair Recommendations

REPAIR TIP	Full part replacement required. Do not drive with shattered glass.
URGENCY	Can be addressed at a local garage. No urgent repair needed.
SURFACE	Very Rough (Severe Damage)
COLOUR	High variation (severe damage)

Online Replacement Part Sources

Amazon India	TyrePlex	Apollo Tyres
------------------------------	--------------------------	------------------------------

AutoScan AI — Offline AI-based car damage detection. Cost estimates are approximate Indian market rates. Consult a certified mechanic before any repair decision.