

Car Damage Analysis Report

Segment: Sedan | Age: 3 yrs

DAMAGE DETECTED — SHATTER on HOOD


Detection Summary

DETECTED PART	Hood	PART CONFIDENCE	71.4%
DAMAGE TYPE	Shatter	DAMAGE CONFIDENCE	52.4%
SEVERITY	MINOR	RISK LEVEL	High
COVERAGE	8.7%	REGIONS FOUND	8


AI Damage Metrics



Part Confidence & Cost Estimate



Computer Vision Analysis



Repair Recommendations

REPAIR TIP	Full part replacement required. Do not drive with shattered glass.
URGENCY	Can be addressed at a local garage. No urgent repair needed.
SURFACE	Very Rough (Severe Damage)
COLOUR	High variation (severe damage)

Online Replacement Part Sources

Amazon India	Flipkart	IndiaMart	Moglix
------------------------------	--------------------------	---------------------------	------------------------

AutoScan AI — Offline AI-based car damage detection. Cost estimates are approximate Indian market rates. Consult a certified mechanic before any repair decision.