SERVICE REPORT

JOB NO : 2727 | 0 | 1 | – | 0 | 0 | 3 | 1 | 7 |

Customer PRICON MICROELECTRONICS INC.	Date 15-AUGUST-2017
Person-In Charge MR. ERIC GAMBOA Dept ENGG.	P.O. No
Tel (63)2-843-0870 Fax (049) 549-3164	Remark SI-1708004/ R1

Job Title MACHINE CHECKING

Model NC1-4(2)-B S/No 00204-6220 Instal/Date 1989 (MFD).

Problem 1. LIGHT CURTAIN SENSOR CONTROL BOX MALFUNCTIONING.

NOTE

1. AS PER TEST RUNNING THIS LIGHT CURTAIN SENSOR CONTROL BOX FROM OTHER AIDA PRESS MACHINE NO - MALFUNCTIONING ENCOUNTERED BUT ANY PROBLEM HAPPEN DUE TO CUSTOMER REQUEST AIDA SNR. ENG'R. NO RESPONSIBILITY.

Measures

1. AS PER CUSTOMER REQUEST REPLACE THIS MALFUNCTIONING LIGHT CURTAIN SENSOR CONTROL BOX FROM OTHER AIDA PRESS MACHINE.
2. AS PER MACHINE TEST RUNNING THE MALFUNCTIONING OF CONTROL BOX IS NOT ENCOUNTERED TO THE CONTROL BOX FROM OTHER AIDA PRESS MACHINE.
3. NOW MACHINE CONDITION CAN OPERATION RUNNING IN INCHING AND SINGLE MODE OF OPERATION.

Date	Man	Dep	AIDA	Arv	Cus	Dep	Cus	Arv	AIDA	Normal	1½	2	Job Done by
15 AUG.		7	00	8	30	11	30	13	00	3			GEORGE

SPARE PART	Qty	U/Price	Amount
LABOUR CHARGES [NORMAL]	3	US$ 25	US$ 75
[1½]			
[2]			
TRANSPORT	1	US$ 25	US$ 25
PACKING & DELIVERY CHARGE			
VAT			
TOTAL			US$ 100

Remark

1. I RECOMMENDED TO CHANGE SOME ELECTRICAL PARTS FOR THIS AIDA PRESS MACHINE DUE TO NOT SO GOOD CONDITION.
2. QUOTATION WILL FOLLOW.

Authorised	Confirm	Incharge
		G. GAMBOA JR-M.

Work carried out to our complete satisfaction

CHARGEABLE

Checked & confirmed by

Name RODERICK F. GAMBOA

Post SF. ENGINEER

Sign

Date 08-15-17

Company Name/Stamp

AIDA GREATER ASIA PHILIPPINES, INC.

CUSTOMER COPY