MESCO
Since 1956
QUALITY MACHINE TOOLS AND ENGINEERING PRODUCTS
OFFICE & DISPLAY: MESCO Building, Reliance corner Brixton Streets, 1603 Pasig City, PHILIPPINES
TELS.: (63-2) 631-1775 . FAX: 631-4028 / 635-0276 . E-MAIL: mesco@mesco.com.ph. WEBSITE: www.mesco.com.ph

CUSTOMER:	PRICON MICRO ELECTRONICS INC.	NAME :	Ms.Avhic
ADDRESS :	No. 14 Ampere St.Brgy.Diezmo, LISP 1	TITLE :	
	Cabuyao,Laguna	CC :	
TEL. NO. :	843-0870 loc 228	CUST. REF.:	SR# 110993/ 110999 DATE: Jan. 03, 2020

SERVICE QUOTATION

No	STK Code	Brand	Description	CODE NO.	PESO U/PRICE	DISC %	NET PRICE	QTY	AMOUNT	DEL
1			SERVICE CHARGE for TSUGAMI VA1-II SN# 10112A		8,000		8,000	1 lot	8,000	
			Total no.of hrs. 3							
			ref. Service Report No. 110993/ 110999 dated 11.29/ 12.09.2019							
			MACHINE PROBLEM: " ATC HANG-UP/ MIS-ALIGNED ATC "							
			*** NOTHING FOLLOWS ***							

Note:

*Please issue P.O. in favor of Mesco or signed conforme at lower right side of this page and fax to Fax# **634-1240** or **635-0276** for Invoice issuance.*

REMARKS:		
	TOTAL AMOUNT	P- 8,000
	Net Amount	8,000
	Vat Exempt	-
	TOTAL NET AMOUNT	P- **8,000**

OTHER TERMS AND CONDITIONS:

Delivery : SERVICE COMPLETED REF SERVICE REPORT ATTACHED	Price Validity :
Pay Terms: 30 days	Foreign Currency Exchange Clause :
	Cancellation Clause :
AUTHORIZED SIGNATURE:	CONFORME ORDERED (Pls print name & sign) :
Prepared by: NC_COLEEN DATE: Jan. 03, 2020	TITLE : DATE:

ALL QUOTES ARE SUBJECT TO CHANGE WITHOUT PRIOR NOTICE

RELIANCE COR. BRIXTON STS., PASIG CITY
TELS.: 631-1775 TO 84 • FAX: (632) 631-4028
EMAIL : mesco@mesco.com.ph
Website : http://www.mesco.com.ph

MESCO INC.
Since 1956
QUALITY MACHINE TOOLS & ENGINEERING PRODUCTS

SR Nº 110993

EC VALIDATION STATUS (Internal Use Only)
a) Customer and Machine Info ☐ OK ☐ NG
b) Workpiece ☐ OK ☐ NG

SERVICE REPORT

CUSTOMER: PRICON
ADDRESS: USP 1
MACHINE: VA1
SERIAL NO.: 10112A CODE NO.:
SERVICEMAN: CMC
DATE: 11/29/19
TIME START: 5:06 PM
TIME FINISH: 6:00 PM
TOTAL HRS.: 1HR TRAVELLING HOURS:
JOB COMPLETED: ☐ YES ☐ NO
INSTALLATION DATE:
WARRANTY: ☐ YES ☐ NO

REPORTED PROBLEM: ATC HANG-UP

WORK TYPE:
☐ Calibration ☐ Repair:
☐ PM ☐ Training:
☐ Installation ☐ Parts Measurement:
☐ Shifting ☐ Others:

WORK DONE:
1. CUSTOMER ENCOUNTER B-AXIS ABNORMAL CURRENT M/C CAUSED TO ATC HANG-UP
2. ACTIVATE KEEP RELAY K22.0 & K40.0 ATC MENU.
3. RECOVER ATC HOME. OK
4. ~~TEST~~ TOOL CHANGE. OK
5. M/C BACK TO PRODUCTION.

☐ PARTS REPLACED ☐ PARTS TO BE REPLACED

PARTS NO.	DESCRIPTION	QTY.

RECOMMENDATIONS:

REMARKS:

PERSON IN CHARGE: Nolasco R. Mendoza
POSITION: Sr. Process Engineer
SIGNATURE:

WHITE - ORIGINAL COPY YELLOW - DEPARTMENT COPY PINK - CUSTOMER COPY

RELIANCE COR. BRIXTON STS., PASIG CITY
TELS.: 631-1775 TO 84 • FAX: (632) 631-4028
EMAIL : mesco@mesco.com.ph
Website : http://www.mesco.com.ph

MESCO INC.
Since 1956
QUALITY MACHINE TOOLS & ENGINEERING PRODUCTS

SR Nº 110996

EC VALIDATION STATUS (Internal Use Only)
a) Customer and Machine Info ☐ OK ☐ NG
b) Workpiece ☐ OK ☐ NG

SERVICE REPORT

CUSTOMER: PRECON
ADDRESS: LISP II, CABUYAO
MACHINE: VAJ
SERIAL NO.: 16126 CODE NO.:
SERVICEMAN: GMC
DATE: 12/9/19
TIME START: 1:30
TIME FINISH: 3:30
TOTAL HRS.: 2HR TRAVELLING HOURS:
JOB COMPLETED: ☐ YES ☐ NO
INSTALLATION DATE:
WARRANTY: ☐ YES ☐ NO

REPORTED PROBLEM: MLS - ALIGN ATC

WORK TYPE:
☐ Calibration ☐ Repair:
☐ PM ☐ Training:
☐ Installation ☐ Parts Measurement:
☐ Shifting ☐ Others:

WORK DONE:
1. ATC HANG DURING TOOL CHANG
2. SOFT THERMAL (OVERLOAD) OCCURED @ ATC (B-AXIS)
3. CHECK ATC ALIGNMENT VS TOOL @ SPINDLE FOUND OFFSET.
4. MECHANICALLY ALIGN ATC ARM.
5. TEST TOOL CHANGE. OK
6. M/C BACK TO PRODUCTION.

☐ PARTS REPLACED ☐ PARTS TO BE REPLACED

PARTS NO.	DESCRIPTION	QTY.

RECOMMENDATIONS:

REMARKS:

PERSON IN CHARGE: Nolasco R. Mendoza
POSITION: Sr. process engineer
SIGNATURE:

WHITE - ORIGINAL COPY YELLOW - DEPARTMENT COPY PINK - CUSTOMER COPY