MESCO, INC.
RELIANCE COR. BRIXTON STS., BRGY. KAPITOLYO, PASIG CITY 1603
TELS.: 8631-1775 to 84 • FAX: (632) 8631-4028
EMAIL : mesco@mesco.com.ph
Website : http://www.mesco.com.ph

MESCO Since 1956

QUALITY MACHINE TOOLS & ENGINEERING PRODUCTS

SR № 122067

EC VALIDATION STATUS (Internal Use Only)
a) Customer and Machine Info ☐ OK ☐ NG
b) Workpiece ☐ OK ☐ NG

SERVICE REPORT

CUSTOMER: PRICON
ADDRESS: CABUYAO LAGUNA
MACHINE: VA1 - II
SERIAL NO.: V013A CODE NO.:

SERVICEMAN: AEM / CMC / MRN
DATE: 04 - 18 - 2022
TIME START: 4:00 pm
TIME FINISH: 4:30 Pm
TOTAL HRS.: TRAVELLING HOURS:

JOB COMPLETED: ☑ YES ☐ NO
INSTALLATION DATE:
WARRANTY: ☐ YES ☑ NO

REPORTED PROBLEM: ABNORMAL CURRENT DURING TOOLCHANGE.

WORK TYPE:
☐ Calibration ☑ Repair:
☐ PM ☐ Training:
☐ Installation ☐ Parts Measurement:
☐ Shifting ☐ Others:

☐ PARTS REPLACED ☐ PARTS TO BE REPLACED

PARTS NO.	DESCRIPTION	QTY.

WORK DONE:
- TEST MANUAL TOOL CHANGE. ALARM APPEARED
- CHECK ATC ALIGNMENT. FOUND MISALIGN.
- LOOSEN ATC ARM BOLT AND PERFORM TEST MISALIGN. OK.
- TEST SEVERAL TOOL CHANGE. OK
- MACHINE NOW BACK TO NORMAL CONDITION.

RECOMMENDATIONS:

REMARKS:

PERSON IN CHARGE: VICKO MENDOZA
POSITION: Sr. Engineer
SIGNATURE:

WHITE - ORIGINAL COPY YELLOW - DEPARTMENT COPY PINK - CUSTOMER COPY

Scanned with CamScanner