RELIANCE COR. BRIXTON STS., PASIG CITY
TELS.: 631-1775 TO 84 • FAX: (632) 631-4028
EMAIL : mesco@mesco.com.ph
Website : http://www.mesco.com.ph

MESCO INC.
Since 1956
QUALITY MACHINE TOOLS & ENGINEERING PRODUCTS

SR Nº 98913

EC VALIDATION STATUS (Internal Use Only)
a) Customer and Machine Info ☐ OK ☐ NG
b) Workpiece ☐ OK ☐ NG

SERVICE REPORT

CUSTOMER: PRICON
ADDRESS: LISP
MACHINE: VA1 -11
SERIAL NO.: 10113A CODE NO.:

SERVICEMAN: AAK / BBR
DATE: 12/28/2018
TIME START: ~~12:20~~ 12:00 pm
TIME FINISH: 1:00
TOTAL HRS.: TRAVELLING HOURS:

JOB COMPLETED: ☑ YES ☐ NO
INSTALLATION DATE:
WARRANTY: ☐ YES ☑ NO

REPORTED PROBLEM: M/C COLLISION / MIS-ALIGN ATC ARM

WORK TYPE:
☐ Calibration ☐ Repair:
☐ PM ☐ Training:
☐ Installation ☐ Parts Measurement:
☐ Shifting ☐ Others:

WORK DONE:
- M/C IS DOWN UPON ARRIVAL
- CHECK ATC, FOUND MIS-ALIGN.
- ~~ADJ~~ ALIGN ATC TO SPINDLE, OK
- DO AUTO TOOL CHANGE, OK
- CONTINUES TOOL CHANGE, OK
- M/C BACK TO OPERATION

☐ PARTS REPLACED ☐ PARTS TO BE REPLACED

PARTS NO.	DESCRIPTION	QTY.

RECOMMENDATIONS:

REMARKS:

PERSON IN CHARGE: N. Mendoza
POSITION: Sr. Engineer
SIGNATURE:

WHITE - ORIGINAL COPY YELLOW - DEPARTMENT COPY PINK - CUSTOMER COPY