NISSEI PLASTIC PHILIPPINES, INC.

Unit 11 Bldg. B Laguna Technopark Standard Factory Bldg. 2 Phase 7
Laguna Technopark-Sez Binan Laguna 4024 Philippines
Tel No 049-544-5670 Fax No 049-544-5647

SERVICE QUOTATION

ATTN: PRICON MICROELECTRONICS INC.,
Mam Rebecca Valenzuela

Q/S NO: QS 220819 002
DATE: August 19, 2022
SERVICE REPORT NO:

We thank you for your recent enquiry.
As requested, we are delighted to submit herewith our official quotation for your kind consideration and approval.

Terms of Payment : 30 days after INVOICE date

Remittance Charge : All the Remittance charge to the remitter side (OUR)
Validity : September 19, 2022
Machine Model : UH1000-80 MC#:
Serial Number : P08R010

DESCRIPTION	Q'TY	U/PRICE	TOTAL
SERVICE FEE			-
Machine Inspection	1	₱9,000	₱9,000 -
(Inspection Based on Nissei Inspection Sheet)			

TOTAL	₱9,000 -

This Quotation is exclusive of PARTS fee and TRAVEL expenses
For details of the contents please refer to attached sheet
*** E.. & O.E.***

NISSEI PLASTIC PHILIPPINES INC.

PREPARED BY:

Anna Marie Almanza
Sales Engineer