NPI MACHINERY, INC.

5TH FLOOR, ORCELL II BUILDING
1611 QUEZON AVENUE, WEST TRIANGLE
QUEZON CITY 1100
TEL. NOS.: 925-17-03 926-74-79; 926-4683
FAX NOS.: 926-30-96

№ 4571

DATE SEPT 11, 2018

SERVICE REPORT

CUSTOMER'S NAME PRICON MICROELECTRONICS INC.	CUST. SIGNATURE
ADDRESS LISP I CABUYAO LAGUNA	
SERVICE BY MELVIN D. MORCILLA	SERVICE MAN SIGN

1) REPAIR ☐	2) EXAMINATION ☐	3) OVERHAUL ☐	4) FITTING ☑	5) SUPERVISION OF START UP ☑

ACTION TAKEN MODEL: EX-16 T-008472
- ROBOT TRANSFER FROM MACHINE 5A TO MACHINE 4A
- CHECK INTERLOCK AND SIGNAL
- TEST RUN ROBOT IN DRY RUN MODE & AUTO MODE.

REMARKS: ROBOT IS NOW READY FOR OPERATION.

RESULT	1) OPERATING WELL	2) OPERATION UNABLE TO BE CHECKED	3) REPAIR WORK REMAINING TO BE DONE

PARTS USED

	PART CODE	NAME OF PART	QTY	UNIT PRICE	AMOUNT
1					
2					
3					
4					
5					
	LABOR CHARGE				
				LABOR AMOUNT	₱ 10,000 - -

TIME STARTED 9:00	TIME FINISHED 13:15	TOTAL TIME 4:15	TRAVEL TIME

NPI Machinery Inc
5th Floor , ORCELL 2 Building,
1611 Quezon Avenue, West Triangle,
Quezon City 1100 Philippines

Telephone Nos: (632) 926-7479

Faximile No.: (632) 920-3096

DATE 12-Sep-18

SERVICE QUOTATION

TO **PRICON MICROELECTRONICS INC.,**

NPISQ NO2018-09-003-1

ADDRESS No. 14 Ampere Street, Barangay Diezmo, Light Industry and Science Park1 (LISP 1), Cabuyao, Laguna

ATTENTION **Ms. Rebecca Valenzuela**

Dear Ms. Rebecca Valenzuela
We are honored to offer our services as follows for the following:

Machine Model EX4G Serial No T-003472

Brief Description of the Trouble or the Work to be done

Robot transfer from machine 5A to machine 14.Check interlock and signal. Test run robot in dry run mode & auto mode.
Remarks: Robot is now ready for operation.

Special Instructions

Service Report No. 4571 dated September 11, 2018.

Machine Type	Working Task	Fee/task	Task	Line Total
EX4G	SERVICE FEE	10,000.00 P/task	1 task	10,000.00 P
			Total	10,000.00 P

Respectfully Yours,

Jon Diaz