NPI MACHINERY, INC.
5TH FLOOR, ORCELL II BUILDING
1611 QUEZON AVENUE, WEST TRIANGLE
QUEZON CITY 1100
TEL. NOS.: 925-17-03 926-74-79; 926-4683
FAX NOS.: 926-30-96

№ 4536

SERVICE REPORT

DATE FEB 27. 2017

CUSTOMER'S NAME PRICON MICROELECTRONICS INC.	CUST. SIGNATURE
ADDRESS LISP I CABUYAO LAGUNA	
SERVICE BY MELVIN D. MORCILLA	SERVICE MAN SIGN

1) REPAIR	2) EXAMINATION	3) OVERHAUL	4) FITTING	5) SUPERVISION OF START UP
☐	☐	☐	☑	☐

ACTION TAKEN MODEL: EXG-150 SN. T-0034104
- TRANSFER OF ROBOT FROM M/C # 1 TO M/C # 4.
- TEST INTERLOCK AND SIGNAL.
- TEST MANUAL OPERATION AND AUTO MODE.
- NOW ROBOT IS READY TO USE.

RESULT	1) OPERATING WELL	2) OPERATION UNABLE TO BE CHECKED	3) REPAIR WORK REMAINING TO BE DONE

PARTS USED

	PART CODE	NAME OF PART	QTY	UNIT PRICE	AMOUNT
1					
2					
3					
4					
5					
	LABOR CHARGE				

TIME STARTED	TIME FINISHED	TOTAL TIME	LABOR AMOUNT	TRAVEL TIME
9:00	16:30	7 HRS	₱ 8,800	

NPI Machinery Inc
5th Floor , ORCELL 2 Building,
1611 Quezon Avenue, West Triangle,
Quezon City 1100 Philippines

Telephone Nos: (632) 926-7479

Faximile No.: (632) 920-3096

DATE 28-Feb-17

SERVICE QUOTATION

TO **PRICON MICROELECTRONICS INC.,**

NPISQ NO2017-02-012-1

ADDRESS No. 14 Ampere Street, Barangay Diezmo, Light Industry and Science Park1 (LISP 1), Cabuyao, Laguna

ATTENTION **Mr. Virglio Garcia**

Dear Mr. Virglio Garcia
We are honored to offer our services as follows for the following:

Machine Model EXG-150 Serial No T0043404

Brief Description of the Trouble or the Work to be done

Transfer of robot from M/C #1 to M/C #4.
Test interlock and signal.
Test manual operation and auto mode.
Now robot is ready to use.

Special Instructions

Service Report No. 4536 dated Feb. 27, 2017

Machine Type	Working Task	Fee/task	Task	Line Total
EXG-150	SERVICE FEE	8,800.00 P/task	1 task	8,800.00 P
			Total	8,800.00 P

Respectfully Yours
for:
Alex Selfaison