**SODICK PHILIPPINES INC**
**Company Regn : CS201501353**
**Company Tin : 008-944-890**
M201 Unit,GRM Bldg.,124 East Science Ave.,cor Trade Ave.,
Laguna Technopark, Binan City, Laguna 4024
TEL#: (049) 544 0936

№ 002653

# SERVICE REPORT

| | | | |
|---|---|---|---|
| CUSTOMER : PRICON | | MACHINE : TR5EH12 | S/N F059 |
| PERSON IN CHARGE : | | CONTROLLER : | S/N |
| COUNTRY : PH | | SOFTWARE VER. : | |
| INSTALLATION DATE | | OPTION : AWT.ATC. OTHERS : | |

| SERVICE DATE | STARTING TIME | FINISHING TIME | TOTAL TIME | ENGINEER |
|---|---|---|---|---|
| 3-24-2021 | 9:30 | 11:00 | 1 HR 30 MIN | KGN, JON |
| | | | HR MIN | |
| | | | HR MIN | |

MATTER OF REQUEST / NATURE OF PROBLEM

- E006716 MOLD AMP FAULT ERROR (OV) RESTART INJECTION MACHINE

DESCRIPTION OF SERVICE

- CHECKED MACHINE MOLD CLOSE/OPEN - NOTICED NOISE ON OPEN/CLOSE
- CHECKED SERVO DRIVER ; REPLACED SERVO DRIVER - OK
- FUNCTION TEST - OK
- DRY RUN - OK

| | | | |
|---|---|---|---|
| ☐ WARRANTY | ☑ SERVICE CHARGE | ☑ COMPLETED | ☐ MONITORING |
| ☐ F.O.C | ☐ SERVICE CONTRACT | ☐ NOT COMPLETE | RE-ARRANGE DATE: |

| PARTS CODE | DESCRIPTION | QTY | PARTS CODE | DESCRIPTION | QTY |
|---|---|---|---|---|---|
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |

**SODICK PHILIPPINES, INC.**

JONA VILLARCA
*Engineer*

ALTHON D. ANDRADE 03/24/21
*Signature / Company's Stamp*

Service's Copy