NISSEI PLASTIC PHILIPPINES, INC.

Unit 11, Building B, Laguna Technopark Standard Factory Building 2, Phase7
Laguna Technopark-SEZ, Biñan, Laguna Tel. No.: (049) 544-5670 Fax No: (049) 544-5647

SERVICE REPORT

No.: A 0955

Customer: PTICON MICROELECTRONICS INC. **Date:** 03 / 20 / 2018

Model: FE80S12H **Mfg. yy/mm:** 1995.9

Serial Number: F08P009 m/c #: **Gts.:** 1583365

Controller: N93C

Reason for Maintenance

- ALARM: SCPU COMMUNICATION ALARM

Action Taken

- FOR TODAY, REPLACED NEW OPTIC CABLE
- 10METERS OPTIC CABLE FROM MONITOR TO SCPU BOARD
- ALARM RESET
- MANUAL TEST FOR ALL FUNCTIONS & MOVEMENTS OKAY
- MACHINE CAN PROCEED TO MASS PRO

SERVICE BY:

1 R. BARTON

2 N. NISHIZAWA

TIME:

Start	End
10 : 00	12 : 00

Total: 2 Hours

Authorized Signature

Service Fee: ₱ 15,000.00

Illustration

SQ No. PO No. SI No. OR No.