NISSEI PLASTIC PHILIPPINES, INC.

Unit 11, Building B, Laguna Technopark Standard Factory Building 2, Phase 7
Laguna Technopark- SEZ, Biñan, Laguna Tel. No.: (049)544-5670 Fax No: (049)544-5647

SERVICE REPORT

No.: A 1514

Customer: PRICON MICROELECTRONICS INC. Date: 01 / 14 / 19

Model: NEX IS III-2EG Machine no. 19A Mfg. yy/mm: 2016.02

Serial Number: H10114020KJ Gts.: 23699 IS

Controller: TACT IV M/C Service Requested By: SIR VER

Reason for Service / Machine Problem

* MACHINE CHECKING DUE NO SIGNAL FOR MOLD OPEN LIMIT (Y3C)

Action Taken

* CHECKED Y3C TERMINAL HAVE OUTPUT SIGNAL (23.1VDC)
* CHECKED RELAY CONNECTION, ROBOT CONNECTION DIRECT TO Y3C
* MAKE LADDER PROGRAM Y35 FOR MOLD OPEN LIMIT SIGNAL
* CHECKED OUTPUT SIGNAL OF Y35 (23.1VDC) OK

SERVICE BY:

1 J. RUBIO 3

2 X. RAMIREZ 4

TIME:

Start	End
10 : 20	12 : 00

Total: 1 hrs. 40 mins.

Service Fee: Php 7,000

REDDIE T. MARTINEZ
Authorized Customer Name & Signature

Recommendation/Parts for Quotation

